

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/27/2016

Submitted Date:

10/27/2016

Document Number:

684902492**FIELD INSPECTION FORM**

Loc ID 432662	Inspector Name: Pesicka, Conor	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>100322</u> Name of Operator: <u>NOBLE ENERGY INC</u> Address: <u>1625 BROADWAY STE 2200</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>Findings:</b> <u>39</u> Number of Comments <u>2</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432648	WELL	PR	04/14/2014	OW	123-37211	WELLS RANCH USX AE 20-69-1HN	PR
432649	WELL	PR	04/14/2014	OW	123-37212	WELLS RANCH AE 20-67HN	PR
432651	WELL	PR	04/14/2014	OW	123-37214	WELLS RANCH AE 20-67-1HN	PR
432653	WELL	PR	04/14/2014	OW	123-37216	WELLS RANCH AE 20-68HN	PR
432654	WELL	PR	04/14/2014	OW	123-37217	WELLS RANCH AE 20-68-1HN	PR
432656	WELL	PR	04/14/2014	OW	123-37219	WELLS RANCH AE 20-66-1HN	PR
432661	WELL	PR	04/14/2014	OW	123-37223	WELLS RANCH AE 20-69HN	PR
433243	WELL	PR	04/14/2014	OW	123-37561	WELLS RANCH AE 20-66HN	PR
437675	WELL	PR	02/01/2016	LO	123-39637	Wells Ranch AE19-662	PR
437676	WELL	PR	02/01/2016	LO	123-39638	Wells Ranch AE19-672	PR
437679	WELL	PR	02/01/2016	LO	123-39641	Wells Ranch AE19-667	PR
437680	WELL	PR	02/01/2016	LO	123-39642	Wells Ranch AE19-677	PR
437681	WELL	PR	02/01/2016	LO	123-39643	Wells Ranch AE19-654	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	No capacity on maintenance tank		
Corrective Action:	Install sign to comply with rule 210	Date:	12/27/2016
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	xsylsol, methanol, corrosion inhibitor, engine oil, coolant		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment around site		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details. (any unused equipment requiring machinery to remove is 90 days instead of 30)	Date:	11/28/2016

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	agricultural		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Vertical Separator	# 20		
Comment:			
Corrective Action:		Date:	
Type: Flare	# 2		
Comment:			

Corrective Action:		Date:	
Type: Compressor	# 4		
Comment:	sales & lift		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 11		
Comment:	1 surge vessel		
Corrective Action:		Date:	
Type: Bird Protectors	# 12		
Comment:			
Corrective Action:		Date:	
Type: LACT	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	solar & telemetry		
Corrective Action:		Date:	
Type: Ancillary equipment	# 11		
Comment:	pumps - 8 methanol, 2 corrosion inhibitor, 1 xsysol		
Corrective Action:		Date:	
Type: Gas Meter Run	# 20		
Comment:	13 lift, 7 apportioned		
Corrective Action:		Date:	
Type: Ancillary equipment	# 10		
Comment:	containers - 4 engine oil, 4 coolant, 2 methanol		
Corrective Action:		Date:	
Type: Plunger Lift	# 13		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 6		
Comment:	3 apportioned, 2 sales, 1 surge vessel		
Corrective Action:		Date:	
Type: Vertical Separator	# 10		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 1	
Comment:	natural gas gen	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV CONCRETE		40.473810,-104.355740
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	60bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	<50 BBLS	PBV FIBERGLASS		40.473830,-104.355680
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	10bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

Contents	#	Capacity	Type	Tanak ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.473910,-104.355170
Comment:	maintenance tank				
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	432648	Type:	WELL	API Number:	123-37211	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
<b>BradenHead</b>									
Comment:	Bradenhead plumbed to surface.								
Corrective Action:						Date:			
Facility ID:	432649	Type:	WELL	API Number:	123-37212	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
<b>BradenHead</b>									
Comment:	Bradenhead plumbed to surface.								
Corrective Action:						Date:			
Facility ID:	432651	Type:	WELL	API Number:	123-37214	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	432653	Type:	WELL	API Number:	123-37216	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
<b>BradenHead</b>									
Comment:	Bradenhead plumbed to surface.								
Corrective Action:						Date:			
Facility ID:	432654	Type:	WELL	API Number:	123-37217	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:						Date:			
<b>Workover</b>									
Comment:	Bradenhead plumbed to surface.								
Corrective Action:						Date:			
Facility ID:	432656	Type:	WELL	API Number:	123-37219	Status:	PR	Insp. Status:	PR

<b><u>Producing Well</u></b>			
Comment:	<a href="#">PR</a>		
Corrective Action:		Date:	
<b><u>BradenHead</u></b>			
Comment:	<a href="#">Bradenhead plumbed to surface.</a>		
Corrective Action:		Date:	
Facility ID: <u>432661</u> Type: <u>WELL</u> API Number: <u>123-37223</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<b><u>Producing Well</u></b>			
Comment:	<a href="#">PR</a>		
Corrective Action:		Date:	
<b><u>BradenHead</u></b>			
Comment:	<a href="#">Bradenhead plumbed to surface.</a>		
Corrective Action:		Date:	
Facility ID: <u>433243</u> Type: <u>WELL</u> API Number: <u>123-37561</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<b><u>Producing Well</u></b>			
Comment:	<a href="#">PR</a>		
Corrective Action:		Date:	
<b><u>BradenHead</u></b>			
Comment:	<a href="#">Bradenhead plumbed to surface.</a>		
Corrective Action:		Date:	
Facility ID: <u>437675</u> Type: <u>WELL</u> API Number: <u>123-39637</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<b><u>Producing Well</u></b>			
Comment:	<a href="#">PR</a>		
Corrective Action:		Date:	
<b><u>BradenHead</u></b>			
Comment:	<a href="#">Bradenhead plumbed to surface.</a>		
Corrective Action:		Date:	
Facility ID: <u>437676</u> Type: <u>WELL</u> API Number: <u>123-39638</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<b><u>Producing Well</u></b>			
Comment:	<a href="#">PR</a>		
Corrective Action:		Date:	
<b><u>BradenHead</u></b>			
Comment:	<a href="#">Bradenhead plumbed to surface.</a>		
Corrective Action:		Date:	

Facility ID:	437679	Type:	WELL	API Number:	123-39641	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	PR								
Corrective Action:						Date:			
<b><u>BradenHead</u></b>									
Comment:	Bradenhead plumbed to surface.								
Corrective Action:						Date:			
Facility ID:	437680	Type:	WELL	API Number:	123-39642	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	PR								
Corrective Action:						Date:			
<b><u>BradenHead</u></b>									
Comment:	Bradenhead plumbed to surface.								
Corrective Action:						Date:			
Facility ID:	437681	Type:	WELL	API Number:	123-39643	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	PR								
Corrective Action:						Date:			
<b><u>BradenHead</u></b>									
Comment:	Bradenhead plumbed to surface.								
Corrective Action:						Date:			

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): NO	
Comment:	Gas to CPF
Pilot:	Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Waddles	Pass			
Gravel	Pass	Gravel	Pass			
Ditches	Pass					
Slope Roughening	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
684902492	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3994437">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3994437</a>
684902493	Unused equipment	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3989019">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3989019</a>
684902494	Unused equipment	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3989020">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3989020</a>
684902495	No capacity on maintenance tank	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3989021">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3989021</a>