

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/04/2016

Submitted Date:

11/07/2016

Document Number:

673403839**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 313308      Waldron, Emily      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 97810Name of Operator: YATES PETROLEUM CORPORATIONAddress: 105 SOUTH 4TH STCity: ARTESIA      State: NM      Zip: 88210**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name   | Phone        | Email                       | Comment |
|----------------|--------------|-----------------------------|---------|
| Crisler, duane | 307-382-4005 | dcrisler@yatespetroleum.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name              | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------------|-------------|
| 285957      | WELL | PR     | 07/01/2015  | GW         | 081-07328 | LANDING STRIP FEDERAL<br>1 | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |   |       |            |
|----------------------|---|-------|------------|
| <b>Signs/Marker:</b> |   |       |            |
| Type                 | TANK LABELS/PLACARDS                    |       |            |
| Comment:             | NO NFPA diamond on produced water tank. |       |            |
| Corrective Action:   | Install sign to comply with Rule 210.d. | Date: | 12/07/2016 |
| Type                 | BATTERY                                 |       |            |
| Comment:             |   |       |            |
| Corrective Action:   |   | Date: |            |
| Type                 | WELLHEAD                                |       |            |
| Comment:             |   |       |            |
| Corrective Action:   |   | Date: |            |

Emergency Contact Number:

Comment: 307-382-4005

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |          |       |  |
|--------------------|----------|-------|--|
| <b>Fencing/:</b>   |          |       |  |
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

|                                 |     |       |                 |
|---------------------------------|-----|-------|-----------------|
| <b>Equipment:</b>               |     |       | corrective date |
| Type: Compressor                | # 1 |       |                 |
| Comment:                        |     |       |                 |
| Corrective Action:              |     | Date: |                 |
| Type: Flare                     | # 2 |       |                 |
| Comment:                        |     |       |                 |
| Corrective Action:              |     | Date: |                 |
| Type: Bird Protectors           | #   |       |                 |
| Comment:                        |     |       |                 |
| Corrective Action:              |     | Date: |                 |
| Type: Horizontal Heater Treater | # 1 |       |                 |
| Comment:                        |     |       |                 |
| Corrective Action:              |     | Date: |                 |

**Tanks and Berms:**

|                    |   |          |           |          |                       |       |
|--------------------|---|----------|-----------|----------|-----------------------|-------|
| Contents           | # | Capacity | Type      | Tanak ID | SE GPS                |       |
| PRODUCED WATER     | 1 | 400 BBLs | STEEL AST |          | 40.764080,-107.539090 |       |
| Comment:           |   |          |           |          |                       |       |
| Corrective Action: |   |          |           |          |                       | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate |                     |                     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          | Date:               |                     |             |

|                    |   |          |           |          |        |  |
|--------------------|---|----------|-----------|----------|--------|--|
| Contents           | # | Capacity | Type      | Tanak ID | SE GPS |  |
| CONDENSATE         | 1 | 400 BBLs | STEEL AST |          | ,      |  |
| Comment:           |   |          |           |          |        |  |
| Corrective Action: |   | Date:    |           |          |        |  |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate |                     |                     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          | Date:               |                     |             |

**Venting:**

|                    |       |  |
|--------------------|-------|--|
| Yes/No             | NO    |  |
| Comment:           |       |  |
| Corrective Action: | Date: |  |

**Flaring:**

|                    |                   |  |
|--------------------|-------------------|--|
| Type               | Ignitor/Combustor |  |
| Comment:           |                   |  |
| Corrective Action: | Date:             |  |

|                             |            |                       |            |                  |
|-----------------------------|------------|-----------------------|------------|------------------|
| <b>Inspected Facilities</b> |            |                       |            |                  |
| Facility ID: 285957         | Type: WELL | API Number: 081-07328 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b>       |            |                       |            |                  |
| Comment:                    |            |                       |            |                  |
| Corrective Action:          |            |                       |            | Date:            |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT