



**photo 1:** Facing south at the beginning of the access road.



**photo 2:** Facing southwest along the access road.



**photo 3:** Facing southwest along the access road.



**photo 4:** Facing southeast toward the location.



photo 5: An electric utility remains at the location.



photo 6: Facing east at the location.



**photo 7:** Facing east along the north fill slope.



**photo 8:** There is a small patch of noxious weeds at the north side of the location.



**photo 9:** Facing toward the east side of the location.



**photo 10:** Facing toward the south cut slope side of the location.