



**photo 1:** Facing northwest at the beginning of the access road.



**photo 2:** Facing west along the access road.



**photo 3:** Facing northeast along the access road.



**photo 4:** Facing north along the access road. Cattle guard in place and maintained.



**photo 5:** Southeast side of the location facing northwest.



**photo 6:** South side of the location facing northwest.



**photo 7:** West side of the location facing east.



**photo 8:** North side of the location facing south.



**photo 9:** Facing east toward the surrounding reference area.