

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/08/2016

Submitted Date:

11/08/2016

Document Number:

685301773**FIELD INSPECTION FORM**
 Loc ID 312063 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 96705Name of Operator: WPX ENERGY PRODUCTION LLCAddress: P O BOX 3102 MS-25-2City: TULSA State: OK Zip: 74101**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name     | Phone        | Email                                       | Comment                |
|------------------|--------------|---|------------------------|
| Labowskie, Steve |              | steve.labowskie@state.co.us                 | COGCC                  |
| Inspection, WPX  | 970-263-2716 | COGCCInspectionReportsSanJuan@wpxenergy.com | WPX Inspection Mailbox |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 216458      | WELL | PR     | 02/21/1997  | GW         | 067-08064 | BONDAD 33-9 24-A | PR          |

**General Comment:**

**Location****Lease Road:**

|                   |        |       |  |
|-------------------|--------|-------|--|
| Type              | Access |       |  |
| comment:          |        |       |  |
| Corrective Action |        | Date: |  |

Overall Good: ☐**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | TANK LABELS/PLACARDS |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |
| Type               | WELLHEAD             |       |  |
| Comment:           |                      |       |  |
| Corrective Action: |                      | Date: |  |

**Emergency Contact Number:**

|                    |  |             |
|--------------------|--|-------------|
| Comment:           |  |             |
| Corrective Action: |  | Date: _____ |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

|                    |               |       |  |
|--------------------|---------------|-------|--|
| Type               | TANK BATTERY  |       |  |
| Comment:           | Post and Wire |       |  |
| Corrective Action: |               | Date: |  |

**Equipment:**

|                                   |                     |       |                 |
|-----------------------------------|---------------------|-------|-----------------|
|                                   |                     |       | corrective date |
| Type: Gas Meter Run               | # 1                 |       |                 |
| Comment:                          |                     |       |                 |
| Corrective Action:                |                     | Date: |                 |
| Type: Flow Line                   | # 1                 |       |                 |
| Comment:                          |                     |       |                 |
| Corrective Action:                |                     | Date: |                 |
| Type: Horizontal Heated Separator | # 1                 |       |                 |
| Comment:                          |                     |       |                 |
| Corrective Action:                |                     | Date: |                 |
| Type: Ancillary equipment         | # 1                 |       |                 |
| Comment:                          | Telemetry Equipment |       |                 |
| Corrective Action:                |                     | Date: |                 |

|                           |          |  |       |
|---------------------------|----------|--|-------|
| Type: Ancillary equipment | # 1      |  |       |
| Comment:                  | Wellhead |  |       |
| Corrective Action:        |          |  | Date: |
| Type: Bird Protectors     | # 1      |  |       |
| Comment:                  |          |  |       |
| Corrective Action:        |          |  | Date: |

**Tanks and Berms:**

|                    |                |          |          |          |        |       |
|--------------------|----------------|----------|----------|----------|--------|-------|
| Contents           | #              | Capacity | Type     | Tanak ID | SE GPS |       |
| PRODUCED WATER     | 1              | OTHER    | Open Top |          | ,      |       |
| Comment:           | Steel Mesh Top |          |          |          |        |       |
| Corrective Action: |                |          |          |          |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 125 BBLS |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |
|                    |          |                     | Date:               |             |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities |        |       |      |             |           |         |    |               |    |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 216458 | Type: | WELL | API Number: | 067-08064 | Status: | PR | Insp. Status: | PR |
| Producing Well       |        |       |      |             |           |         |    |               |    |
| Comment:             |        | PR    |      |             |           |         |    |               |    |
| Corrective Action:   |        |       |      |             |           |         |    | Date:         |    |

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

|                  |                 |                         |                       |  |                          |         |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
| Gravel           | Pass            | Gravel                  | Pass                  |  |                          |         |
| Compaction       | Pass            | Compaction              | Pass                  | Material Handling And Spill Prevention | Pass                     |         |

Comment:

Corrective Action:

Date:

**Pits:** ☒ NO SURFACE INDICATION OF PIT