

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/09/2016

Submitted Date:

11/09/2016

Document Number:

680000708**FIELD INSPECTION FORM**

Loc ID 433705 Inspector Name: QUINT, CRAIG On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10422Name of Operator: PRONGHORN OPERATING LLCAddress: 8400 E PRENTICE AVENUE #1000City: GREENWOOD State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Kuenzler, Zane	720-261-2019	zanekuenzler@kfrcorp.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433698	WELL	PR	11/01/2013	OW	017-07759	Evan 2	PR

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Dirt road through farm ground		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:	228 Caprock pumping unit		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Elec panel, Cathodic rectifier, Chemical tank w/BMP		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Elec motor		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
			CENTRALIZED BATTERY		38.854460,-102.369930
Comment:	Central Battery f/(Chesnee 2, Evans 2) 1770' E				
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:	2" casing vent is shut off.		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

### Location Construction

Location ID: 433698 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

#### Form 2A COAs:

**Comment:** No issues observed

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

#### Wildlife BMPs:

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_

Date: \_\_\_\_\_

#### On Site Inspection (305):

##### Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

##### Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

##### LGD Contact Information:

Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Agreed to Attend: \_\_\_\_\_

##### Summary of Landowner Issues:

\_\_\_\_\_

##### Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

##### Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

Inspected Facilities									
Facility ID:	433698	Type:	WELL	API Number:	017-07759	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, Central Battery f/(Chesnee 2, Evans 2) 1770' E @ 38.854460,-102.369930								
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: DRY LAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment [Anchors have been removed](#)

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: DRY LAND \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	

Comment: [Access and unused areas of the location are farmed over.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT