

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
11/10/2016
Submitted Date:
11/10/2016
Document Number:
674004592

FIELD INSPECTION FORM

Loc ID 331960 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269145	WELL	PR	08/01/2006	GW	123-21630	HOUSTON P 17-17	PR

General Comment:

(This area is intentionally left blank for general comments.)

Location

Overall Good:

Signs/Marker:

Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	LOCATION		
Comment:	Portable pipe cattle fencing		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 269145 Type: WELL API Number: 123-21630 Status: PR Insp. Status: PR

Cement

Cement Contractor

Contractor Name: _____

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: Witnessed:
Reliance Wire Line cut casing with jet cutter at 770 ft.
Casing loose and circulation established.

Corrective Action:

Date: _____

Workover

Comment: Leed

Corrective Action:

Date: _____

COGCC Comments

Comment	User	Date
Routine PA inspection. Company representative on location: Jay Chandler	carlilec	11/10/2016