

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/10/2016

Submitted Date:

11/10/2016

Document Number:

666802726

### FIELD INSPECTION FORM

Loc ID 335102 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100185  
 Name of Operator: ENCANA OIL & GAS (USA) INC  
 Address: 370 17TH ST STE 1700  
 City: DENVER State: CO Zip: 80202-

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272024	WELL	PR	12/01/2004	GW	045-09998	GMR 34-3 (B34NW)	PR
272025	WELL	PR	11/23/2004	GW	045-09999	GMR 34-2 (B34NW)	PR
272026	WELL	PR	12/27/2004	GW	045-10000	GMR 34-1B (B34NW)	PR
272027	WELL	PR	11/29/2004	GW	045-10001	GMR 34-2B (B34NW)	PR

**General Comment:**

[shared facilities with location ID 335095.](#)



Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tanak ID	SE GPS		
OTHER	1	OTHER	PLASTIC AST		,		
Comment:		chemical unit, centralized battery					
Corrective Action:				Date:			

**Paint**

Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:							
Corrective Action:				Date:			

Contents	#	Capacity	Type	Tanak ID	SE GPS		
CONDENSATE	4	500 BBLs	STEEL AST		39.487532,-107.760875		
Comment:							
Corrective Action:				Date:			

**Paint**

Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:				Date:			

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	<u>272024</u>	Type:	<u>WELL</u>	API Number:	<u>045-09998</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>272025</u>	Type:	<u>WELL</u>	API Number:	<u>045-09999</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>272026</u>	Type:	<u>WELL</u>	API Number:	<u>045-10000</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>272027</u>	Type:	<u>WELL</u>	API Number:	<u>045-10001</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<b>Producing Well</b>									
Comment:	<u>Plunger lift</u>								
Corrective Action:					Date:				

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Berms	Pass					
Seeding	Pass					
Gravel	Pass					
		Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT