

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/03/2016

Submitted Date:

11/04/2016

Document Number:

675203552**FIELD INSPECTION FORM**

|  |                                    |   |                   |   |
|--|------------------------------------|---|-------------------|---|
| Loc ID<br>336055   | Inspector Name:<br>CONKLIN, CURTIS | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | <b>Status Summary:</b><br><input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION<br><input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED<br><input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED |
| <b>Operator Information:</b><br>OGCC Operator Number: <u>16700</u><br>Name of Operator: <u>CHEVRON USA INC</u><br>Address: <u>6301 DEAUVILLE BLVD</u><br>City: <u>MIDLAND</u> State: <u>TX</u> Zip: <u>79706</u> |                                    |   |                   | <b>Findings:</b><br>1 Number of Comments<br>0 Number of Corrective Actions<br><input type="checkbox"/> Corrective Action Response Requested   |

**Contact Information:**

| Contact Name  | Phone          | Email               | Comment                         |
|---------------|----------------|---------------------|---------------------------------|
| Justus, Julie | (970) 257-6042 | jjustus@chevron.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 295343      | WELL | PR     | 08/01/2011  | GW         | 045-15732 | SKR 598-36-AV-02 | PR          |
| 297055      | WELL | PR     | 05/29/2011  | GW         | 045-16273 | SKR 598-36-AV-15 | PR          |
| 297056      | WELL | PR     | 07/13/2011  | GW         | 045-16274 | SKR 598-36-AV-16 | PR          |
| 297057      | WELL | PR     | 06/03/2011  | GW         | 045-16275 | SKR 598-36-AV-17 | PR          |
| 297058      | WELL | PR     | 08/11/2011  | GW         | 045-16276 | SKR 598-36-AV-18 | PR          |
| 297060      | WELL | PR     | 06/29/2011  | GW         | 045-16278 | SKR 598-36-AV-20 | PR          |
| 297061      | WELL | PR     | 05/25/2011  | GW         | 045-16279 | SKR 598-36-AV-21 | PR          |
| 297062      | WELL | PR     | 06/29/2011  | GW         | 045-16280 | SKR 598-36-AV-22 | PR          |
| 297063      | WELL | PR     | 06/22/2011  | GW         | 045-16281 | SKR 598-36-AV-03 | PR          |
| 297064      | WELL | PR     | 07/21/2011  | GW         | 045-16282 | SKR 598-36-AV-04 | PR          |
| 297080      | WELL | PR     | 06/18/2011  | GW         | 045-16287 | SKR 598-36-AV-05 | PR          |
| 297081      | WELL | PR     | 06/16/2011  | GW         | 045-16288 | SKR 598-36-AV-07 | PR          |
| 297082      | WELL | PR     | 06/25/2011  | GW         | 045-16289 | SKR 598-36-AV-01 | PR          |
| 297083      | WELL | PR     | 06/08/2011  | GW         | 045-16290 | SKR 598-36-AV-13 | PR          |
| 297084      | WELL | PR     | 06/11/2011  | GW         | 045-16291 | SKR 598-36-AV-11 | PR          |
| 297085      | WELL | PR     | 07/17/2011  | GW         | 045-16292 | SKR 598-36-AV-12 | PR          |
| 297086      | WELL | PR     | 07/21/2011  | GW         | 045-16293 | SKR 598-36-AV-08 | PR          |
| 297087      | WELL | PR     | 06/12/2011  | GW         | 045-16294 | SKR 598-36-AV-09 | PR          |
| 297088      | WELL | PR     | 07/28/2011  | GW         | 045-16295 | SKR 598-36-AV-06 | PR          |
| 297089      | WELL | PR     | 07/15/2011  | GW         | 045-16296 | SKR 598-36-AV-14 | PR          |
| 297090      | WELL | PR     | 05/27/2011  | GW         | 045-16297 | SKR 598-36-AV-19 | PR          |
| 297091      | WELL | PR     | 11/01/2014  | GW         | 045-16298 | SKR 598-36-AV-10 | PR          |

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|------|------|--------|--|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

| Contents           | #                    | Capacity | Type      | Tanak ID | SE GPS |                      |
|--------------------|----------------------|----------|-----------|----------|--------|----------------------|
| PRODUCED WATER     | 1                    | 500 BBLS | STEEL AST |          | ,      |                      |
| Comment:           | <input type="text"/> |          |           |          |        |                      |
| Corrective Action: | <input type="text"/> |          |           |          | Date:  | <input type="text"/> |

**Paint**

|                  |                      |                      |
|------------------|----------------------|----------------------|
| Condition        | Adequate             | <input type="text"/> |
| Other (Content)  | <input type="text"/> |                      |
| Other (Capacity) | <input type="text"/> |                      |
| Other (Type)     | <input type="text"/> |                      |

**Berms**

| Type               | Capacity             | Permeability (Wall) | Permeability (Base) | Maintenance                |
|--------------------|----------------------|---------------------|---------------------|----------------------------|
| Metal              | Adequate             | Walls Sufficent     | Base Sufficent      | Adequate                   |
| Comment:           | <input type="text"/> |                     |                     |                            |
| Corrective Action: | <input type="text"/> |                     |                     | Date: <input type="text"/> |

**Venting:**

|                    |                      |                      |                            |
|--------------------|----------------------|----------------------|----------------------------|
| Yes/No             | NO                   | <input type="text"/> |                            |
| Comment:           | <input type="text"/> |                      |                            |
| Corrective Action: | <input type="text"/> |                      | Date: <input type="text"/> |

**Flaring:**

|                    |                      |                      |
|--------------------|----------------------|----------------------|
| Type               | <input type="text"/> |                      |
| Comment:           | <input type="text"/> |                      |
| Corrective Action: | <input type="text"/> |                      |
|                    | Date:                | <input type="text"/> |

| Inspected Facilities       |                   |                              |                   |                         |
|----------------------------|-------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>295343</u> | Type: <u>WELL</u> | API Number: <u>045-15732</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>297055</u> | Type: <u>WELL</u> | API Number: <u>045-16273</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>297056</u> | Type: <u>WELL</u> | API Number: <u>045-16274</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>297057</u> | Type: <u>WELL</u> | API Number: <u>045-16275</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>297058</u> | Type: <u>WELL</u> | API Number: <u>045-16276</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>297060</u> | Type: <u>WELL</u> | API Number: <u>045-16278</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>297061</u> | Type: <u>WELL</u> | API Number: <u>045-16279</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>297062</u> | Type: <u>WELL</u> | API Number: <u>045-16280</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>297063</u> | Type: <u>WELL</u> | API Number: <u>045-16281</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>297064</u> | Type: <u>WELL</u> | API Number: <u>045-16282</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>297080</u> | Type: <u>WELL</u> | API Number: <u>045-16287</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>297081</u> | Type: <u>WELL</u> | API Number: <u>045-16288</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>297082</u> | Type: <u>WELL</u> | API Number: <u>045-16289</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>297083</u> | Type: <u>WELL</u> | API Number: <u>045-16290</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>297084</u> | Type: <u>WELL</u> | API Number: <u>045-16291</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>297085</u> | Type: <u>WELL</u> | API Number: <u>045-16292</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>297086</u> | Type: <u>WELL</u> | API Number: <u>045-16293</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>297087</u> | Type: <u>WELL</u> | API Number: <u>045-16294</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>297088</u> | Type: <u>WELL</u> | API Number: <u>045-16295</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |

|              |        |       |      |             |           |         |    |               |    |
|--------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 297089 | Type: | WELL | API Number: | 045-16296 | Status: | PR | Insp. Status: | PR |
| Facility ID: | 297090 | Type: | WELL | API Number: | 045-16297 | Status: | PR | Insp. Status: | PR |
| Facility ID: | 297091 | Type: | WELL | API Number: | 045-16298 | Status: | PR | Insp. Status: | PR |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            | Pass            | Compaction              | Pass                  |               |                          |         |
| Compaction       | Pass            | Gravel                  | Pass                  |               |                          |         |
| Gravel           | Pass            | Check Dams              | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 675203552    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3993669">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3993669</a> |