

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/03/2016

Submitted Date:

11/04/2016

Document Number:

675203553

FIELD INSPECTION FORM

Loc ID 336050	Inspector Name: CONKLIN, CURTIS	On-Site Inspection <input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 1 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
2A Doc Num: _____			

Operator Information:			
OGCC Operator Number: 16700			
Name of Operator: CHEVRON USA INC			
Address: 6301 DEAUVILLE BLVD			
City: MIDLAND	State: TX	Zip: 79706	

Contact Information:

Contact Name	Phone	Email	Comment
Justus, Julie	(970) 257-6042	jjustus@chevron.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295965	WELL	PR	08/02/2012	GW	045-15865	SKR 698-09-AV-04	PR
298601	WELL	PR	07/19/2012	GW	045-17281	SKR 698-09-AV-03	PR
298602	WELL	PR	07/01/2013	GW	045-17282	SKR 698-09-AV-22	PR
298603	WELL	PR	09/01/2012	GW	045-17283	SKR 698-09-AV-21	PR
298604	WELL	PR	08/01/2013	GW	045-17284	SKR 698-09-AV-20	PR
298605	WELL	PR	08/31/2012	GW	045-17285	SKR 698-09-AV-19	PR
298606	WELL	PR	07/01/2013	GW	045-17286	SKR 698-09-AV-18	PR
298607	WELL	PR	07/01/2013	GW	045-17287	SKR 698-09-AV-16	PR
298608	WELL	PR	08/25/2012	GW	045-17288	SKR 698-09-AV-15	PR
298610	WELL	PR	08/08/2012	GW	045-17289	SKR 698-09-AV-14	PR
298611	WELL	PR	08/23/2012	GW	045-17290	SKR 698-09-AV-13	PR
298612	WELL	PR	12/13/2011	GW	045-17291	SKR 698-09-AV-12	PR
298613	WELL	PR	12/10/2011	GW	045-17292	SKR 698-09-AV-11	PR
298614	WELL	PR	12/20/2011	GW	045-17293	SKR 698-09-AV-10	PR
298615	WELL	PR	12/24/2011	GW	045-17294	SKR 698-09-AV-09	PR
298616	WELL	PR	07/01/2013	GW	045-17295	SKR 698-09-AV-08	PR
298617	WELL	PR	12/07/2011	GW	045-17296	SKR 698-09-AV-07	PR
298618	WELL	PR	07/17/2012	GW	045-17297	SKR 698-09-AV-01	PR
298619	WELL	PR	07/31/2012	GW	045-17298	SKR 698-09-AV-02	PR
298620	WELL	PR	07/22/2012	GW	045-17299	SKR 698-09-AV-05	PR
298621	WELL	PR	08/29/2012	GW	045-17300	SKR 698-09-AV-17	PR
298622	WELL	PR	04/14/2012	GW	045-17301	SKR 698-09-AV-06	PR
412116	WELL	PR	08/01/2013	GW	045-18438	SKR 698-09-AV-24	PR
412117	WELL	PR	07/14/2012	GW	045-18439	SKR 698-09-AV-23	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type
Comment:
Corrective Action:
Date:

Inspected Facilities				
Facility ID: <u>295965</u>	Type: <u>WELL</u>	API Number: <u>045-15865</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298601</u>	Type: <u>WELL</u>	API Number: <u>045-17281</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298602</u>	Type: <u>WELL</u>	API Number: <u>045-17282</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298603</u>	Type: <u>WELL</u>	API Number: <u>045-17283</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298604</u>	Type: <u>WELL</u>	API Number: <u>045-17284</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298605</u>	Type: <u>WELL</u>	API Number: <u>045-17285</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298606</u>	Type: <u>WELL</u>	API Number: <u>045-17286</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298607</u>	Type: <u>WELL</u>	API Number: <u>045-17287</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298608</u>	Type: <u>WELL</u>	API Number: <u>045-17288</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298610</u>	Type: <u>WELL</u>	API Number: <u>045-17289</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298611</u>	Type: <u>WELL</u>	API Number: <u>045-17290</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298612</u>	Type: <u>WELL</u>	API Number: <u>045-17291</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298613</u>	Type: <u>WELL</u>	API Number: <u>045-17292</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298614</u>	Type: <u>WELL</u>	API Number: <u>045-17293</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298615</u>	Type: <u>WELL</u>	API Number: <u>045-17294</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298616</u>	Type: <u>WELL</u>	API Number: <u>045-17295</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298617</u>	Type: <u>WELL</u>	API Number: <u>045-17296</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298618</u>	Type: <u>WELL</u>	API Number: <u>045-17297</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298619</u>	Type: <u>WELL</u>	API Number: <u>045-17298</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Inspector Name: CONKLIN, CURTIS

Facility ID:	298620	Type:	WELL	API Number:	045-17299	Status:	PR	Insp. Status:	PR
Facility ID:	298621	Type:	WELL	API Number:	045-17300	Status:	PR	Insp. Status:	PR
Facility ID:	298622	Type:	WELL	API Number:	045-17301	Status:	PR	Insp. Status:	PR
Facility ID:	412116	Type:	WELL	API Number:	045-18438	Status:	PR	Insp. Status:	PR
Facility ID:	412117	Type:	WELL	API Number:	045-18439	Status:	PR	Insp. Status:	PR

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Berms	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203553	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3993670