

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/03/2016

Submitted Date:

11/04/2016

Document Number:

675203552**FIELD INSPECTION FORM**

Loc ID 336055	Inspector Name: CONKLIN, CURTIS	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>16700</u> Name of Operator: <u>CHEVRON USA INC</u> Address: <u>6301 DEAUVILLE BLVD</u> City: <u>MIDLAND</u> State: <u>TX</u> Zip: <u>79706</u>				<b>Findings:</b> 1 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Justus, Julie	(970) 257-6042	jjustus@chevron.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295343	WELL	PR	08/01/2011	GW	045-15732	SKR 598-36-AV-02	PR
297055	WELL	PR	05/29/2011	GW	045-16273	SKR 598-36-AV-15	PR
297056	WELL	PR	07/13/2011	GW	045-16274	SKR 598-36-AV-16	PR
297057	WELL	PR	06/03/2011	GW	045-16275	SKR 598-36-AV-17	PR
297058	WELL	PR	08/11/2011	GW	045-16276	SKR 598-36-AV-18	PR
297060	WELL	PR	06/29/2011	GW	045-16278	SKR 598-36-AV-20	PR
297061	WELL	PR	05/25/2011	GW	045-16279	SKR 598-36-AV-21	PR
297062	WELL	PR	06/29/2011	GW	045-16280	SKR 598-36-AV-22	PR
297063	WELL	PR	06/22/2011	GW	045-16281	SKR 598-36-AV-03	PR
297064	WELL	PR	07/21/2011	GW	045-16282	SKR 598-36-AV-04	PR
297080	WELL	PR	06/18/2011	GW	045-16287	SKR 598-36-AV-05	PR
297081	WELL	PR	06/16/2011	GW	045-16288	SKR 598-36-AV-07	PR
297082	WELL	PR	06/25/2011	GW	045-16289	SKR 598-36-AV-01	PR
297083	WELL	PR	06/08/2011	GW	045-16290	SKR 598-36-AV-13	PR
297084	WELL	PR	06/11/2011	GW	045-16291	SKR 598-36-AV-11	PR
297085	WELL	PR	07/17/2011	GW	045-16292	SKR 598-36-AV-12	PR
297086	WELL	PR	07/21/2011	GW	045-16293	SKR 598-36-AV-08	PR
297087	WELL	PR	06/12/2011	GW	045-16294	SKR 598-36-AV-09	PR
297088	WELL	PR	07/28/2011	GW	045-16295	SKR 598-36-AV-06	PR
297089	WELL	PR	07/15/2011	GW	045-16296	SKR 598-36-AV-14	PR
297090	WELL	PR	05/27/2011	GW	045-16297	SKR 598-36-AV-19	PR
297091	WELL	PR	11/01/2014	GW	045-16298	SKR 598-36-AV-10	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume			
------	------	--------	--	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS	
PRODUCED WATER	1	500 BBLS	STEEL AST		,	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>

**Paint**

Condition	Adequate	<input type="text"/>
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>

**Venting:**

Yes/No	NO	<input type="text"/>	
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

**Flaring:**

Type	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	
	Date:	<input type="text"/>

Inspected Facilities				
Facility ID: <u>295343</u>	Type: <u>WELL</u>	API Number: <u>045-15732</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>297055</u>	Type: <u>WELL</u>	API Number: <u>045-16273</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>297056</u>	Type: <u>WELL</u>	API Number: <u>045-16274</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>297057</u>	Type: <u>WELL</u>	API Number: <u>045-16275</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>297058</u>	Type: <u>WELL</u>	API Number: <u>045-16276</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>297060</u>	Type: <u>WELL</u>	API Number: <u>045-16278</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>297061</u>	Type: <u>WELL</u>	API Number: <u>045-16279</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>297062</u>	Type: <u>WELL</u>	API Number: <u>045-16280</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>297063</u>	Type: <u>WELL</u>	API Number: <u>045-16281</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>297064</u>	Type: <u>WELL</u>	API Number: <u>045-16282</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>297080</u>	Type: <u>WELL</u>	API Number: <u>045-16287</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>297081</u>	Type: <u>WELL</u>	API Number: <u>045-16288</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>297082</u>	Type: <u>WELL</u>	API Number: <u>045-16289</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>297083</u>	Type: <u>WELL</u>	API Number: <u>045-16290</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>297084</u>	Type: <u>WELL</u>	API Number: <u>045-16291</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>297085</u>	Type: <u>WELL</u>	API Number: <u>045-16292</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>297086</u>	Type: <u>WELL</u>	API Number: <u>045-16293</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>297087</u>	Type: <u>WELL</u>	API Number: <u>045-16294</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>297088</u>	Type: <u>WELL</u>	API Number: <u>045-16295</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Facility ID:	297089	Type:	WELL	API Number:	045-16296	Status:	PR	Insp. Status:	PR
Facility ID:	297090	Type:	WELL	API Number:	045-16297	Status:	PR	Insp. Status:	PR
Facility ID:	297091	Type:	WELL	API Number:	045-16298	Status:	PR	Insp. Status:	PR

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			
Gravel	Pass	Check Dams	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203552	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4000239">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4000239</a>