

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/03/2016

Submitted Date:

11/04/2016

Document Number:

675203542**FIELD INSPECTION FORM**
 Loc ID 336051 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 6301 DEAUVILLE BLVDCity: MIDLAND State: TX Zip: 79706**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Justus, Julie	(970) 257-6042	jjustus@chevron.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298733	WELL	XX	07/18/2015	LO	045-17396	SKR-698-09-BV 22	XX
298734	WELL	XX	07/18/2015	LO	045-17397	SKR-698-09-BV 21	XX
298735	WELL	XX	07/18/2015	LO	045-17398	SKR-698-09-BV 20	XX
298736	WELL	XX	07/18/2015	LO	045-17399	SKR-698-09-BV 19	XX
298737	WELL	XX	07/18/2015	LO	045-17400	SKR-698-09-BV 18	XX
298738	WELL	XX	07/18/2015	LO	045-17401	SKR-698-09-BV 17	XX
298739	WELL	XX	07/18/2015	LO	045-17402	SKR-698-09-BV 16	XX
298740	WELL	XX	07/18/2015	LO	045-17403	SKR-698-09-BV 15	XX
298741	WELL	XX	07/18/2015	LO	045-17404	SKR-698-09-BV 14	XX
298742	WELL	XX	07/18/2015	LO	045-17405	SKR-698-09-BV 13	XX
298743	WELL	XX	07/18/2015	LO	045-17406	SKR-698-09-BV 12	XX
298744	WELL	XX	07/18/2015	LO	045-17407	SKR-698-09-BV 11	XX
298745	WELL	XX	07/18/2015	LO	045-17408	SKR-698-09-BV 09	XX
298746	WELL	XX	07/18/2015	LO	045-17409	SKR-698-09-BV 08	XX
298747	WELL	XX	07/18/2015	LO	045-17410	SKR-698-09-BV 07	XX
298748	WELL	XX	07/18/2015	LO	045-17411	SKR-698-09-BV 06	XX
298749	WELL	XX	07/18/2015	LO	045-17412	SKR-698-09-BV 05	XX
298750	WELL	XX	07/18/2015	LO	045-17413	SKR-698-09-BV 04	XX
298751	WELL	XX	07/18/2015	LO	045-17414	SKR-698-09-BV 02	XX
298752	WELL	XX	07/18/2015	LO	045-17415	SKR-698-09-BV 01	XX
298836	WELL	XX	07/18/2015	LO	045-17431	SKR-698-09-BV 10	XX
298837	WELL	XX	07/18/2015	LO	045-17432	SKR-698-09-BV 03	XX
412812	WELL	XX	07/18/2015	LO	045-18626	SKR-698-09-BV 24	XX
412813	WELL	XX	07/18/2015	LO	045-18625	SKR-698-09-BV 23	XX

General Comment:

Inspected Facilities				
Facility ID: <u>298733</u>	Type: <u>WELL</u>	API Number: <u>045-17396</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>298734</u>	Type: <u>WELL</u>	API Number: <u>045-17397</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>298735</u>	Type: <u>WELL</u>	API Number: <u>045-17398</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>298736</u>	Type: <u>WELL</u>	API Number: <u>045-17399</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>298737</u>	Type: <u>WELL</u>	API Number: <u>045-17400</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>298738</u>	Type: <u>WELL</u>	API Number: <u>045-17401</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>298739</u>	Type: <u>WELL</u>	API Number: <u>045-17402</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>298740</u>	Type: <u>WELL</u>	API Number: <u>045-17403</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>298741</u>	Type: <u>WELL</u>	API Number: <u>045-17404</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>298742</u>	Type: <u>WELL</u>	API Number: <u>045-17405</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>298743</u>	Type: <u>WELL</u>	API Number: <u>045-17406</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>298744</u>	Type: <u>WELL</u>	API Number: <u>045-17407</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>298745</u>	Type: <u>WELL</u>	API Number: <u>045-17408</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>298746</u>	Type: <u>WELL</u>	API Number: <u>045-17409</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>298747</u>	Type: <u>WELL</u>	API Number: <u>045-17410</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>298748</u>	Type: <u>WELL</u>	API Number: <u>045-17411</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>298749</u>	Type: <u>WELL</u>	API Number: <u>045-17412</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>298750</u>	Type: <u>WELL</u>	API Number: <u>045-17413</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>
Facility ID: <u>298751</u>	Type: <u>WELL</u>	API Number: <u>045-17414</u>	Status: <u>XX</u>	Insp. Status: <u>XX</u>

Facility ID: 298752	Type: WELL	API Number: 045-17415	Status: XX	Insp. Status: XX
Facility ID: 298836	Type: WELL	API Number: 045-17431	Status: XX	Insp. Status: XX
Facility ID: 298837	Type: WELL	API Number: 045-17432	Status: XX	Insp. Status: XX
Facility ID: 412812	Type: WELL	API Number: 045-18626	Status: XX	Insp. Status: XX
Facility ID: 412813	Type: WELL	API Number: 045-18625	Status: XX	Insp. Status: XX

COGCC Comments

Comment	User	Date
Conductors have been set. Approved APD on file.	conklinc	11/04/2016

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203542	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4000227
675203547	Wells with conductors	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3993612