

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/03/2016

Submitted Date:

11/04/2016

Document Number:

675203551**FIELD INSPECTION FORM**

Loc ID 336054 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 6301 DEAUVILLE BLVDCity: MIDLAND State: TX Zip: 79706**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Justus, Julie	(970) 257-6042	jjustus@chevron.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
276277	WELL	PR	02/16/2006	GW	045-10436	SKINNER RIDGE 598-25-2	PR
296980	WELL	PR	02/01/2011	GW	045-16242	SKR 598-25-CV-20	PR
296981	WELL	PR	10/10/2010	GW	045-16243	SKR 598-25-CV-13	PR
296982	WELL	PR	11/15/2010	GW	045-16244	SKR 598-25-CV-12	PR
296983	WELL	PR	10/21/2010	GW	045-16245	SKR 598-25-CV-10	PR
296984	WELL	PR	10/09/2010	GW	045-16246	SKR 598-25-CV-09	PR
296985	WELL	PR	11/10/2010	GW	045-16247	SKR 598-25-CV-17	PR
296986	WELL	PR	12/08/2010	GW	045-16248	SKR 598-25-CV-15	PR
296987	WELL	PR	11/10/2010	GW	045-16249	SKR 598-25-CV-16	PR
296988	WELL	PR	11/18/2010	GW	045-16250	SKR 598-25-CV-14	PR
296989	WELL	PR	01/11/2011	GW	045-16251	SKR 598-25-CV-22	PR
296990	WELL	PR	01/17/2011	GW	045-16252	SKR 598-25-CV-21	PR
296991	WELL	PR	11/10/2010	GW	045-16253	SKR 598-25-CV-18	PR
296992	WELL	PR	10/02/2010	GW	045-16254	SKR 598-25-CV-03	PR
296993	WELL	PR	12/20/2010	GW	045-16255	SKR 598-25-CV-01	PR
296994	WELL	PR	11/10/2010	GW	045-16256	SKR 598-25-CV-19	PR
296995	WELL	PR	09/15/2010	GW	045-16257	SKR 598-25-CV-02	PR
296996	WELL	PR	10/15/2010	GW	045-16258	SKR 598-25-CV-06	PR
296997	WELL	PR	10/09/2010	GW	045-16259	SKR 598-25-CV-11	PR
296998	WELL	PR	10/16/2010	GW	045-16260	SKR 598-25-CV-08	PR
296999	WELL	PR	05/22/2012	GW	045-16261	SKR 598-25-CV-07	PR
297000	WELL	PR	10/08/2010	GW	045-16262	SKR 598-25-CV-05	PR
297001	WELL	PR	09/18/2010	GW	045-16263	SKR 598-25-CV-04	PR

General Comment:

--

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS	
PRODUCED WATER	1	400 BBLS	STEEL AST		,	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>

Paint

Condition	Adequate	<input type="text"/>
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>

Venting:

Yes/No	NO	<input type="text"/>
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	
	Date:	<input type="text"/>

Flaring:

Type	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	
	Date:	<input type="text"/>

Inspected Facilities				
Facility ID: <u>276277</u>	Type: <u>WELL</u>	API Number: <u>045-10436</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296980</u>	Type: <u>WELL</u>	API Number: <u>045-16242</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296981</u>	Type: <u>WELL</u>	API Number: <u>045-16243</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296982</u>	Type: <u>WELL</u>	API Number: <u>045-16244</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296983</u>	Type: <u>WELL</u>	API Number: <u>045-16245</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296984</u>	Type: <u>WELL</u>	API Number: <u>045-16246</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296985</u>	Type: <u>WELL</u>	API Number: <u>045-16247</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296986</u>	Type: <u>WELL</u>	API Number: <u>045-16248</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296987</u>	Type: <u>WELL</u>	API Number: <u>045-16249</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296988</u>	Type: <u>WELL</u>	API Number: <u>045-16250</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296989</u>	Type: <u>WELL</u>	API Number: <u>045-16251</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296990</u>	Type: <u>WELL</u>	API Number: <u>045-16252</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296991</u>	Type: <u>WELL</u>	API Number: <u>045-16253</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296992</u>	Type: <u>WELL</u>	API Number: <u>045-16254</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296993</u>	Type: <u>WELL</u>	API Number: <u>045-16255</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296994</u>	Type: <u>WELL</u>	API Number: <u>045-16256</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296995</u>	Type: <u>WELL</u>	API Number: <u>045-16257</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296996</u>	Type: <u>WELL</u>	API Number: <u>045-16258</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>296997</u>	Type: <u>WELL</u>	API Number: <u>045-16259</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Facility ID:	296998	Type:	WELL	API Number:	045-16260	Status:	PR	Insp. Status:	PR
Facility ID:	296999	Type:	WELL	API Number:	045-16261	Status:	PR	Insp. Status:	PR
Facility ID:	297000	Type:	WELL	API Number:	045-16262	Status:	PR	Insp. Status:	PR
Facility ID:	297001	Type:	WELL	API Number:	045-16263	Status:	PR	Insp. Status:	PR

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203551	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4000237