

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
11/04/2016
Submitted Date:
11/04/2016
Document Number:
680000697

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: QUINT, CRAIG On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 66561
Name of Operator: OXY USA INC
Address: PO BOX 27757 #110
City: HOUSTON State: TX Zip: 77227-

Findings:

13 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Kosola, Jason		jason.kosola@state.co.us	
Center, Rex	719-688-9372 cell	rex@strachanexploration.com	
Strachan, Stephen	(303) 785-7006	sms@strachanexploration.com	
Ramos, Martha		martha.ramos@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
255965	GAS GATHERING SYSTEM	AC	11/03/2004		-	McCLAVE GAS COMPRESSOR STATION	AC

General Comment:

Facility is located in a compressor/Storage yard. Abatements for inspection ([doc#663600195](#)) have been addressed

Location			
Lease Road:			
Type	Access		
comment:	Access off of county road A.5		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Facility sign at entrance, Sign has been updated to current operator		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Stencils and stickers		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Compressor/Storage yard fenced with wire		
Corrective Action:			Date:
Equipment:			
Type: Gas Meter Run	# 6		corrective date
Comment:	5-Inlet, 1-Discharge		
Corrective Action:			Date:
Type: Dehydrator	# 1		
Comment:	With a reboiler		
Corrective Action:			Date:
Type: Compressor	# 2		
Comment:	In a metal compressor building		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	2 inlet scrubbers		
Corrective Action:			Date:

Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	ECD with scrubber on skid		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
METHANOL	1	200 BBLs	STEEL AST		38.272800,-102.816410
Comment:	210 bbl steel tank				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		38.272690,-102.816390
Comment:	112 bbl Fiberglass water tank, Shared berm				
Corrective Action:					Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	2	200 BBLs	STEEL AST		38.272690,-102.816390
Comment:	2-210 bbl steel tanks				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO			
Comment:				
Corrective Action:			Date:	

Flaring:

Type				
Comment:				
Corrective Action:			Date:	

Inspected FacilitiesFacility ID: 255965 Type: GAS API Number: - Status: AC Insp. Status: AC**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680000697	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4000289
680000698	McClave Compressor Station	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3994225