

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/03/2016

Submitted Date:

11/04/2016

Document Number:

675203540**FIELD INSPECTION FORM**

Loc ID 336048	Inspector Name: CONKLIN, CURTIS	On-Site Inspection <input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED							
2A Doc Num: _____			Findings: 3 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested							
Operator Information: OGCC Operator Number: <u>16700</u> Name of Operator: <u>CHEVRON USA INC</u> Address: <u>6301 DEAUVILLE BLVD</u> City: <u>MIDLAND</u> State: <u>TX</u> Zip: <u>79706</u>										
Contact Information:										
<table border="1" style="width:100%"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>Justus, Julie</td> <td>(970) 257-6042</td> <td>jjustus@chevron.com</td> <td>All Inspections</td> </tr> </table>				Contact Name	Phone	Email	Comment	Justus, Julie	(970) 257-6042	jjustus@chevron.com
Contact Name	Phone	Email	Comment							
Justus, Julie	(970) 257-6042	jjustus@chevron.com	All Inspections							

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295998	WELL	WO	11/17/2015	GW	045-15897	SKR 598-36-BV-01	TA
297728	WELL	WO	11/17/2015	GW	045-16929	SKR 598-36-BV-22	TA
297729	WELL	WO	11/17/2015	GW	045-16930	SKR 598-36-BV-13	TA
297730	WELL	WO	11/17/2015	GW	045-16931	SKR 598-36-BV-15	TA
297731	WELL	WO	11/17/2015	GW	045-16932	SKR 598-36-BV-17	TA
297732	WELL	WO	11/17/2015	GW	045-16933	SKR 598-36-BV-19	TA
297733	WELL	WO	11/17/2015	GW	045-16934	SKR 598-36-BV-21	TA
297734	WELL	WO	11/17/2015	GW	045-16935	SKR 598-36-BV-09	TA
297735	WELL	WO	11/17/2015	GW	045-16936	SKR 598-36-BV-11	TA
297736	WELL	WO	11/17/2015	GW	045-16937	SKR 598-36-BV-07	TA
297737	WELL	WO	11/17/2015	GW	045-16938	SKR 598-36-BV-03	TA
297738	WELL	WO	11/17/2015	GW	045-16393	SKR 598-36-BV-05	TA
297739	WELL	WO	11/17/2015	GW	045-16939	SKR 598-36-BV-20	TA
297740	WELL	WO	11/17/2015	GW	045-16940	SKR 598-36-BV-18	TA
297741	WELL	WO	11/17/2015	GW	045-16941	SKR 598-36-BV-02	TA
297742	WELL	WO	11/17/2015	GW	045-16942	SKR 598-36-BV-16	TA
297743	WELL	WO	11/17/2015	GW	045-16943	SKR 598-36-BV-12	TA
297744	WELL	WO	11/17/2015	GW	045-16944	SKR 598-36-BV-04	TA
297745	WELL	WO	11/17/2015	GW	045-16945	SKR 598-36-BV-06	TA
297793	WELL	TA	11/17/2015	GW	045-16966	SKR 598-36-BV-10	TA
297794	WELL	WO	11/17/2015	GW	045-16967	SKR 598-36-BV-08	TA
297795	WELL	WO	11/17/2015	GW	045-16968	SKR 598-36-BV-14	TA

General Comment:[Approved Form 4s on file for all wells continued TA status.](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

STORAGE OF SUPL

Comment: 6 Separator skids, 1 shed, 22 wellheads, and 1 truck box.

Corrective Action:

Date:

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities				
Facility ID: <u>295998</u>	Type: <u>WELL</u>	API Number: <u>045-15897</u>	Status: <u>WO</u>	Insp. Status: <u>TA</u>
Facility ID: <u>297728</u>	Type: <u>WELL</u>	API Number: <u>045-16929</u>	Status: <u>WO</u>	Insp. Status: <u>TA</u>
Facility ID: <u>297729</u>	Type: <u>WELL</u>	API Number: <u>045-16930</u>	Status: <u>WO</u>	Insp. Status: <u>TA</u>
Facility ID: <u>297730</u>	Type: <u>WELL</u>	API Number: <u>045-16931</u>	Status: <u>WO</u>	Insp. Status: <u>TA</u>
Facility ID: <u>297731</u>	Type: <u>WELL</u>	API Number: <u>045-16932</u>	Status: <u>WO</u>	Insp. Status: <u>TA</u>
Facility ID: <u>297732</u>	Type: <u>WELL</u>	API Number: <u>045-16933</u>	Status: <u>WO</u>	Insp. Status: <u>TA</u>
Facility ID: <u>297733</u>	Type: <u>WELL</u>	API Number: <u>045-16934</u>	Status: <u>WO</u>	Insp. Status: <u>TA</u>
Facility ID: <u>297734</u>	Type: <u>WELL</u>	API Number: <u>045-16935</u>	Status: <u>WO</u>	Insp. Status: <u>TA</u>
Facility ID: <u>297735</u>	Type: <u>WELL</u>	API Number: <u>045-16936</u>	Status: <u>WO</u>	Insp. Status: <u>TA</u>
Facility ID: <u>297736</u>	Type: <u>WELL</u>	API Number: <u>045-16937</u>	Status: <u>WO</u>	Insp. Status: <u>TA</u>
Facility ID: <u>297737</u>	Type: <u>WELL</u>	API Number: <u>045-16938</u>	Status: <u>WO</u>	Insp. Status: <u>TA</u>
Facility ID: <u>297738</u>	Type: <u>WELL</u>	API Number: <u>045-16393</u>	Status: <u>WO</u>	Insp. Status: <u>TA</u>
Facility ID: <u>297739</u>	Type: <u>WELL</u>	API Number: <u>045-16939</u>	Status: <u>WO</u>	Insp. Status: <u>TA</u>
Facility ID: <u>297740</u>	Type: <u>WELL</u>	API Number: <u>045-16940</u>	Status: <u>WO</u>	Insp. Status: <u>TA</u>
Facility ID: <u>297741</u>	Type: <u>WELL</u>	API Number: <u>045-16941</u>	Status: <u>WO</u>	Insp. Status: <u>TA</u>
Facility ID: <u>297742</u>	Type: <u>WELL</u>	API Number: <u>045-16942</u>	Status: <u>WO</u>	Insp. Status: <u>TA</u>
Facility ID: <u>297743</u>	Type: <u>WELL</u>	API Number: <u>045-16943</u>	Status: <u>WO</u>	Insp. Status: <u>TA</u>
Facility ID: <u>297744</u>	Type: <u>WELL</u>	API Number: <u>045-16944</u>	Status: <u>WO</u>	Insp. Status: <u>TA</u>
Facility ID: <u>297745</u>	Type: <u>WELL</u>	API Number: <u>045-16945</u>	Status: <u>WO</u>	Insp. Status: <u>TA</u>

Facility ID:	297793	Type:	WELL	API Number:	045-16966	Status:	TA	Insp. Status:	TA
Facility ID:	297794	Type:	WELL	API Number:	045-16967	Status:	WO	Insp. Status:	TA
Facility ID:	297795	Type:	WELL	API Number:	045-16968	Status:	WO	Insp. Status:	TA

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203540	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4000223