

## Final Reclamation- Bond Release



**Photo 1.** Photo taken from approximate center location, facing West. Photo shows vegetation over the reclamation area.

## Final Reclamation- Bond Release



**Photo 2.** Photo taken from approximate center location, facing North. Photo shows vegetation over the reclamation area. The northern and eastern cut slopes are evident but appear to be stabilized with vegetation.

## Final Reclamation- Bond Release



**Photo 3.** Photo taken from approximate center location, facing East. Photo shows vegetation over the reclamation area. The eastern cut slope is evident but appears to be stabilized with vegetation.

## Final Reclamation- Bond Release



**Photo 4.** Photo taken from approximate center location, facing South. Photo shows vegetation over the reclamation area.