



Photo 1. View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is progressing with vegetation such as smooth brome (*Bromus inermis*), squirreltail (*Elymus elymoides*), and sand dropseed (*Sporobolus* sp.).



Photo 2. View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 3. View of the southern portion of the project area from the southwestern corner facing eastward.



Photo 4. View of the project area from the southwestern corner facing center.



Photo 5. View of the western portion of the project area from the southwestern corner facing northward.