

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/01/2016

Submitted Date:

11/14/2016

Document Number:

674703294**FIELD INSPECTION FORM**
 Loc ID 335812 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275414	WELL	SI	01/28/2007	GW	045-13540	N.PARACHUE WF01D E16 596	RI
275418	WELL	PA	10/21/2012	GW	045-13537	N. PARACHUTE CP12D-16 E16 5	RI
291064	WELL	PA	10/21/2012	DA	045-14280	N. PARACHUTE CP13B-16 E16 59	RI

General Comment:

Inspected Facilities

Facility ID: <u>275414</u>	Type: <u>WELL</u>	API Number: <u>045-13540</u>	Status: <u>SI</u>	Insp. Status: <u>RI</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>275418</u>	Type: <u>WELL</u>	API Number: <u>045-13537</u>	Status: <u>PA</u>	Insp. Status: <u>RI</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Facility ID: <u>291064</u>	Type: <u>WELL</u>	API Number: <u>045-14280</u>	Status: <u>PA</u>	Insp. Status: <u>RI</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: [N.PARACHUE WF01D Cellar and conductor closed Form 6 Subsequent report doc. # 400344272.](#)
[N. PARACHUTE CP12D-16 Form 6 Subsequent report doc. # 400344333.](#)
[N. PARACHUTE CP13B-16 Form 6 Subsequent report doc. # 400345805](#)

Corrective Action: _____ Date _____

Overall Final Reclamation	Pass	Well Release on Active Location <input checked="" type="checkbox"/>	Multi-Well Location <input checked="" type="checkbox"/>
---------------------------	------	---	---

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674703328	No evidence of Plugged and Abandoned wells	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4002457