

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
11/08/2016  
Submitted Date:  
11/08/2016  
Document Number:  
681901698

**FIELD INSPECTION FORM**

Loc ID 305447 Inspector Name: HELGELAND, GARY On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 370 17TH STREET #2170  
City: DENVER State: CO Zip: 80202

**Findings:**

30 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
		Cogcc.inspections@crestone pr.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434333	WELL	DG	10/17/2016	LO	123-38104	Woolley Sosa 2A-7H-E168	DG
434334	WELL	XX	08/06/2015	LO	123-38105	Woolley Becky 2F-7H-E168	XX
434335	WELL	DG	10/23/2016	LO	123-38106	Woolley Sosa 2D-7H-E168	DG
434336	WELL	DG	11/01/2016	LO	123-38107	Woolley Becky 2D-7H-E168	DG
434337	WELL	DG	10/18/2016	LO	123-38108	Woolley Sosa 2B-7H-E168	DG
434338	WELL	DG	10/30/2016	LO	123-38109	Woolley Becky 2B-7H-E168	DG
434339	WELL	DG	10/24/2016	LO	123-38110	Woolley Sosa 2E-7H-E168	DG
434340	WELL	DG	10/29/2016	LO	123-38111	Woolley Becky 2A-7H-E168	DG
434341	WELL	DG	11/02/2016	LO	123-38112	Woolley Becky 2E-7H-E168	DG
434342	WELL	DG	10/26/2016	LO	123-38113	Woolley Sosa 2F-7H-E168	DG
434343	WELL	XX	08/06/2015	LO	123-38114	Woolley Becky 2H-7H-E168	XX
436731	WELL	DG	10/31/2016	LO	123-39241	Woolley Becky 2C-7H-E168	DG
436733	WELL	XX	04/08/2016	LO	123-39242	Woolley Becky 2G-7H-E168	XX
436738	WELL	DG	10/19/2016	LO	123-39245	Woolley Sosa 2C-7H-E168	DG
436739	WELL	DG	10/30/2016	LO	123-39246	Woolley Sosa 2G-7H-E168	DG

**General Comment:**

**Inspected Facilities**

Facility ID: 434333 Type: WELL API Number: 123-38104 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: ENSIGN 122 Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: Surface casing cemented. Surface rig moved off location. Waiting on drilling rig.  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead not installed.  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Completion**

Operation: \_\_\_\_\_  
 Date Flowback: \_\_\_\_\_  
 Contractor: \_\_\_\_\_  
Comment: \_\_\_\_\_  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 434334 Type: WELL API Number: 123-38105 Status: XX Insp. Status: XX

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: Surface casing cemented. Surface rig moved off location. Waiting on drilling rig.  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead not installed.  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 434335 Type: WELL API Number: 123-38106 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids**

**Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:** Surface casing cemented. Surface rig moved off location. Waiting on drilling rig. Bradenhead not installed.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

**Comment:** Bradenhead not installed.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 434336 Type: WELL API Number: 123-38107 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids**

**Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:** Surface casing cemented. Surface rig moved off location. Waiting on drilling rig. Bradenhead not installed.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

**Comment:** Bradenhead not installed.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 434337 Type: WELL API Number: 123-38108 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids**

**Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_  
 Comment: Surface casing cemented. Surface rig moved off location. Waiting on drilling rig. Bradenhead not installed.  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead not installed.  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 434338 Type: WELL API Number: 123-38109 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**  
 Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**  
 Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_  
 Comment: Surface casing cemented. Surface rig moved off location. Waiting on drilling rig. Bradenhead not installed.  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead not installed.  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 434339 Type: WELL API Number: 123-38110 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**  
 Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**  
 Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_  
 Comment: Surface casing cemented. Surface rig moved off location. Waiting on drilling rig. Bradenhead not installed.  
 Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead not installed.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 434340 Type: WELL API Number: 123-38111 Status: DG Insp. Status: DG

**Well Drilling**

Rig: Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_

Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_

Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids**

**Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_

Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: Surface casing cemented. Surface rig moved off location. Waiting on drilling rig. Bradenhead not installed.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead not installed.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 434341 Type: WELL API Number: 123-38112 Status: DG Insp. Status: DG

**Well Drilling**

Rig: Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_

Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_

Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids**

**Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_

Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: Surface casing cemented. Surface rig moved off location. Waiting on drilling rig. Bradenhead not installed.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead not installed.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 434342 Type: WELL API Number: 123-38113 Status: DG Insp. Status: DG

**Well Drilling**

Rig: Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_

Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: Surface casing cemented. Surface rig moved off location. Waiting on drilling rig. Bradenhead not installed.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead not installed.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 434343 Type: WELL API Number: 123-38114 Status: XX Insp. Status: XX

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: Surface casing cemented. Surface rig moved off location. Waiting on drilling rig. Bradenhead not installed.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead not installed.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 436731 Type: WELL API Number: 123-39241 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: Surface casing cemented. Surface rig moved off location. Waiting on drilling rig. Bradenhead not installed.

Corrective Action:	Date:
--------------------	-------

**BradenHead**

Comment: Bradenhead not installed.	Date:
Corrective Action:	Date:

Facility ID: 436733	Type: WELL	API Number: 123-39242	Status: XX	Insp. Status: XX
---------------------	------------	-----------------------	------------	------------------

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: Surface casing cemented. Surface rig moved off location. Waiting on drilling rig. Bradenhead not installed.	Date:
Corrective Action:	Date:

**BradenHead**

Comment: Bradenhead not installed.	Date:
Corrective Action:	Date:

Facility ID: 436738	Type: WELL	API Number: 123-39245	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: Surface casing cemented. Surface rig moved off location. Waiting on drilling rig. Bradenhead not installed.	Date:
Corrective Action:	Date:

**BradenHead**

Comment: Bradenhead not installed.	Date:
Corrective Action:	Date:

Facility ID: 436739	Type: WELL	API Number: 123-39246	Status: DG	Insp. Status: DG
---------------------	------------	-----------------------	------------	------------------

**Well Drilling**

**Rig:** Rig Name: \_\_\_\_\_ Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: \_\_\_\_\_ Access Sign: \_\_\_\_\_

**Well Control Equipment:**  
 Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids Management:**  
 Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: \_\_\_\_\_ Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:** Surface casing cemented. Surface rig moved off location. Waiting on drilling rig. Bradenhead not installed.

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

**Comment:** Bradenhead not installed.

Corrective Action:  Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681901698	INSPECTION APPROVED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4002581">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4002581</a>