

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/15/2016

Submitted Date:

11/15/2016

Document Number:

674103840**FIELD INSPECTION FORM**

Loc ID 318915	Inspector Name: Rickard, Jeff	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 18 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested																																																																															
Operator Information: OGCC Operator Number: <u>47120</u> Name of Operator: <u>KERR MCGEE OIL & GAS ONSHORE LP</u> Address: <u>P O BOX 173779</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-</u>																																																																																			
Contact Information: <table border="1"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>, General</td> <td></td> <td>COGCCinspections@Anadarko.com</td> <td>All Inspections, send to Paul Avant as well</td> </tr> </table>					Contact Name	Phone	Email	Comment	, General		COGCCinspections@Anadarko.com	All Inspections, send to Paul Avant as well																																																																							
Contact Name	Phone	Email	Comment																																																																																
, General		COGCCinspections@Anadarko.com	All Inspections, send to Paul Avant as well																																																																																
Inspected Facilities: <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr> <td>242458</td> <td>WELL</td> <td>PR</td> <td>02/12/1998</td> <td>GW</td> <td>123-10249</td> <td>PHILLIP CAMENISCH GAS UT. 2</td> <td>PR</td> </tr> <tr> <td>426466</td> <td>WELL</td> <td>PR</td> <td>06/06/2013</td> <td>GW</td> <td>123-34699</td> <td>BERGER 5-2</td> <td>PR</td> </tr> <tr> <td>426474</td> <td>WELL</td> <td>PR</td> <td>05/06/2015</td> <td>GW</td> <td>123-34705</td> <td>BERGER 4-2</td> <td>PR</td> </tr> <tr> <td>426530</td> <td>WELL</td> <td>PR</td> <td>03/01/2015</td> <td>GW</td> <td>123-34717</td> <td>BERGER 29-2</td> <td>PR</td> </tr> <tr> <td>426531</td> <td>WELL</td> <td>PR</td> <td>03/01/2015</td> <td>GW</td> <td>123-34718</td> <td>BERGER 3-2</td> <td>PR</td> </tr> <tr> <td>426535</td> <td>WELL</td> <td>PR</td> <td>08/12/2013</td> <td>OW</td> <td>123-34719</td> <td>BERGER 31-2</td> <td>TA</td> </tr> <tr> <td>426536</td> <td>WELL</td> <td>PR</td> <td>06/06/2013</td> <td>GW</td> <td>123-34720</td> <td>BERGER 21-2</td> <td>PR</td> </tr> <tr> <td>426542</td> <td>WELL</td> <td>PR</td> <td>06/06/2013</td> <td>GW</td> <td>123-34724</td> <td>BERGER 28-2</td> <td>PR</td> </tr> <tr> <td>426546</td> <td>WELL</td> <td>PR</td> <td>08/12/2013</td> <td>GW</td> <td>123-34726</td> <td>BERGER 6-2</td> <td>PR</td> </tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	242458	WELL	PR	02/12/1998	GW	123-10249	PHILLIP CAMENISCH GAS UT. 2	PR	426466	WELL	PR	06/06/2013	GW	123-34699	BERGER 5-2	PR	426474	WELL	PR	05/06/2015	GW	123-34705	BERGER 4-2	PR	426530	WELL	PR	03/01/2015	GW	123-34717	BERGER 29-2	PR	426531	WELL	PR	03/01/2015	GW	123-34718	BERGER 3-2	PR	426535	WELL	PR	08/12/2013	OW	123-34719	BERGER 31-2	TA	426536	WELL	PR	06/06/2013	GW	123-34720	BERGER 21-2	PR	426542	WELL	PR	06/06/2013	GW	123-34724	BERGER 28-2	PR	426546	WELL	PR	08/12/2013	GW	123-34726	BERGER 6-2	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																												
242458	WELL	PR	02/12/1998	GW	123-10249	PHILLIP CAMENISCH GAS UT. 2	PR																																																																												
426466	WELL	PR	06/06/2013	GW	123-34699	BERGER 5-2	PR																																																																												
426474	WELL	PR	05/06/2015	GW	123-34705	BERGER 4-2	PR																																																																												
426530	WELL	PR	03/01/2015	GW	123-34717	BERGER 29-2	PR																																																																												
426531	WELL	PR	03/01/2015	GW	123-34718	BERGER 3-2	PR																																																																												
426535	WELL	PR	08/12/2013	OW	123-34719	BERGER 31-2	TA																																																																												
426536	WELL	PR	06/06/2013	GW	123-34720	BERGER 21-2	PR																																																																												
426542	WELL	PR	06/06/2013	GW	123-34724	BERGER 28-2	PR																																																																												
426546	WELL	PR	08/12/2013	GW	123-34726	BERGER 6-2	PR																																																																												

Contact Name	Phone	Email	Comment
, General		COGCCinspections@Anadarko.com	All Inspections, send to Paul Avant as well

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242458	WELL	PR	02/12/1998	GW	123-10249	PHILLIP CAMENISCH GAS UT. 2	PR
426466	WELL	PR	06/06/2013	GW	123-34699	BERGER 5-2	PR
426474	WELL	PR	05/06/2015	GW	123-34705	BERGER 4-2	PR
426530	WELL	PR	03/01/2015	GW	123-34717	BERGER 29-2	PR
426531	WELL	PR	03/01/2015	GW	123-34718	BERGER 3-2	PR
426535	WELL	PR	08/12/2013	OW	123-34719	BERGER 31-2	TA
426536	WELL	PR	06/06/2013	GW	123-34720	BERGER 21-2	PR
426542	WELL	PR	06/06/2013	GW	123-34724	BERGER 28-2	PR
426546	WELL	PR	08/12/2013	GW	123-34726	BERGER 6-2	PR

General Comment:

Inspected Facilities				
Facility ID: 242458	Type: WELL	API Number: 123-10249	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment: PR				
Corrective Action:		Date:		
<u>BradenHead</u>				
Comment: Braden head is exposed at surface.				
Corrective Action:		Date:		
Facility ID: 426466	Type: WELL	API Number: 123-34699	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment: PR				
Corrective Action:		Date:		
<u>BradenHead</u>				
Comment: Braden head is exposed at surface.				
Corrective Action:		Date:		
Facility ID: 426474	Type: WELL	API Number: 123-34705	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment: PR				
Corrective Action:		Date:		
<u>BradenHead</u>				
Comment: Braden head is exposed at surface.				
Corrective Action:		Date:		
Facility ID: 426530	Type: WELL	API Number: 123-34717	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment: PR				
Corrective Action:		Date:		
<u>BradenHead</u>				
Comment: Braden head is exposed at surface.				
Corrective Action:		Date:		
Facility ID: 426531	Type: WELL	API Number: 123-34718	Status: PR	Insp. Status: PR
<u>Producing Well</u>				
Comment: PR				
Corrective Action:		Date:		

BradenHead

Comment: Braden head is exposed at surface.

Corrective Action:

Date: _____

Facility ID: 426535 Type: WELL API Number: 123-34719 Status: PR Insp. Status: TA

Facility ID: 426536 Type: WELL API Number: 123-34720 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Comment: Braden head is exposed at surface.

Corrective Action:

Date: _____

Facility ID: 426542 Type: WELL API Number: 123-34724 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Comment: Braden head is exposed at surface.

Corrective Action:

Date: _____

Facility ID: 426546 Type: WELL API Number: 123-34726 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Comment: Braden head is exposed at surface.

Corrective Action:

Date: _____

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): YES	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____

Date Interim Reclamation Completed: _____

Land Use: IMPROVED PASTURE

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? PassProduction areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IMPROVED PASTURE _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Location inventory has not changed since last inspection.	rickardj	11/15/2016