

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/12/2016

Submitted Date:

11/15/2016

Document Number:

680401089**FIELD INSPECTION FORM**
 Loc ID 428197 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 77330Name of Operator: SG INTERESTS I LTDAddress: 922 EAST 2ND AVENUECity: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	<a href="#">Field Inspector</a>
,	970-385-0696	inspections@sginterests.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428196	WELL	WO	10/05/2012	SI	051-06107	ECK 12-90-1 1	WO
431411	WELL	XX	01/12/2015	LO	051-06113	Eck WDW 2	ND
431413	WELL	XX	01/12/2015	LO	051-06114	Eck 12-90-1 3	ND

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action		Date:	
Type	Main		
comment:			
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel fence at wellhead.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:	SW corner of pad.		
Corrective Action:		Date:	

Type: Gas Meter Run	# 1	
Comment:	Inside tank berms.	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	3	400 BBLs	HEATED STEEL AST		39.047871,-107.389954
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>428196</u>	Type:	<u>WELL</u>	API Number:	<u>051-06107</u>	Status:	<u>WO</u>	Insp. Status:	<u>WO</u>
Facility ID:	<u>431411</u>	Type:	<u>WELL</u>	API Number:	<u>051-06113</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>431413</u>	Type:	<u>WELL</u>	API Number:	<u>051-06114</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_

Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: OTHER, RANGELAND

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? Pass Segregated soils have been replaced? \_\_\_\_\_**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_ P \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: RANGELAND

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date:

**Pits:** ☐ NO SURFACE INDICATION OF PIT