

**From:** [Donahue, Jessica](#)  
**To:** [Spry ORourke, Linda](#); [Cathy Ventling \(Catherine\\_Ventling@blm.gov\)](#)  
**Cc:** [Vrooman, Alan](#); [Lindholm, Stan](#)  
**Subject:** Wagon Track 12-6  
**Date:** Wednesday, September 28, 2011 12:46:28 PM  
**Attachments:** [Wagon Track 12-6 Soils Results 9-16-11.pdf](#)

---

Linda and Cathy,

Please find attached the latest soil test results from the Wagon Track 12-6 remediation. It shows everything to be below Table 910-1 levels, except for the Arsenic which was shown to be higher than standard in the background samples taken at the beginning of the process.

Please let me know if you need any further information, or what forms are required from here on to close this issue out.

Thanks,

Jessica Donahue  
Regulatory Technician  
Black Hills Exploration and Production  
1515 Wynkoop St.  
Suite 500  
Denver, CO 80202  
Phone: 720-210-1333  
Cell: 303-945-9703  
Fax: 303-566-3344  
Email: [jessica.donahue@blackhillscorp.com](mailto:jessica.donahue@blackhillscorp.com)

---

This electronic message transmission contains information from Black Hills Corporation, its affiliate or subsidiary, which may be confidential or privileged. The information is intended to be for the use of the individual or entity named above. If you are not the intended recipient, be aware the disclosure, copying, distribution or use of the contents of this information is prohibited. If you received this electronic transmission in error, please reply to sender immediately; then delete this message without copying it or further reading.