

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401148053
Date Received:
11/14/2016

FIR RESOLUTION FORM

CA Summary:
1 of 3 CAs from the FIR responded to on this Form
0 CA Completed
1 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96705
Name of Operator: WPX ENERGY PRODUCTION LLC
Address: P O BOX 3102 MS-25-2
City: TULSA State: OK Zip: 74101
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
General		COGCCinspectionreportsSanJuan@wpxenergy.com
Russ Knight	5054861826	donald.knight@wpxenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680601045
Inspection Date: 10/26/2016 FIR Submit Date: 11/04/2016 FIR Status:

Inspected Operator Information:

Company Name: WPX ENERGY PRODUCTION LLC Company Number: 96705
Address: P O BOX 3102 MS-25-2
City: TULSA State: OK Zip: 74101

LOCATION - Location ID: 333487

Location Name: DOCAR GAS UNIT-N33N8W Number: 26SEnw County: LA PLATA
Qtrqtr: SENW Sec: 26 Twp: 33N Range: 8W Meridian: N
Latitude: 37.077640 Longitude: -107.690720

FACILITY - API Number: 05-067-00 Facility ID: 214010

Facility Name: DOCAR GAS UNIT Number: 1
Qtrqtr: SENW Sec: 26 Twp: 33N Range: 8W Meridian: N
Latitude: 37.077640 Longitude: -107.690720

CORRECTIVE ACTIONS:

3 CA# 53900

Corrective Action: Stormwater controls are needed to control stormwater erosion and sedimentation within the northeastern corner of the project area. Date: 12/09/2016

Response: FACTUAL REVIEW REQUEST

Basis for Review: Equipment is not owned or controlled by the operator

Operator Comment: This location was drilled in 1962. WPX has historically used the anchor pattern as the template for the project area size on locations which do not have a well use agreement on file. However, this well has not had a well servicing rig on it since 1991, so no anchors exist. A typical rig anchor pattern is 60' x 120'. If a well use

agreement exists, please direct WPX or provide WPX with a copy of the document. The erosion and sedimentation mentioned on page 5 of the document and captured in photograph #6 is approximately 86 feet east of our location - well outside the project area. WPX does not have the authority to alter or remove anything that is located outside our project area. See attached figure.

COGCC Decision: **Not Approved**

COGCC Representative:

COGCC Supervisor:

WPX is the operator on record for this location (333487) and is therefore responsible for corrective actions documented on the location on the required due date. Operator is responsible for the entire location disturbed by oil and gas operations until final reclamation release. Not just the production areas. During the field inspection and aerial map review, it is evident that the extent of disturbance for the location goes beyond the production area shown on the map attached to this document (provided by WPX). Stormwater controls are needed in the northeastern portion of the project area as noted in the inspection.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: LACEY GRANILLO

Signed: _____

Title: PERMITTING TECH II

Date: 11/14/2016 10:55:04 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401148053	FIR RESOLUTION SUBMITTED
401148189	arial map

Total Attach: 2 Files