

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/08/2016

Submitted Date:

11/10/2016

Document Number:

666802723**FIELD INSPECTION FORM**
 Loc ID 334959 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name     | Phone | Email                        | Comment |
|------------------|-------|------------------------------|---------|
| Contact, General |       | cogcc.inspections@encana.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 277039      | WELL | PR     | 07/06/2006  | GW         | 045-10585 | GMU 34-8D (H34NW) | PR          |
| 277040      | WELL | PR     | 06/06/2006  | GW         | 045-10584 | GMU 34-8 (H34NW)  | PR          |
| 277041      | WELL | PR     | 07/19/2006  | GW         | 045-10583 | GMR 34-1 (H34NW)  | PR          |
| 277043      | WELL | PR     | 11/23/2005  | GW         | 045-10581 | GMR 34-7B (H34NW) | PR          |
| 277381      | WELL | PR     | 10/23/2006  | GW         | 045-10695 | GMU 34-9 (H34NW)  | PR          |
| 277382      | WELL | PR     | 06/23/2006  | GW         | 045-10696 | GMU 34-9D (H34NW) | PR          |

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

|                    |                      |       |  |
|--------------------|----------------------|-------|--|
| Type               | BATTERY              |       |  |
| Comment:           | AIRS ID 045-1612-003 |       |  |
| Corrective Action: |                      | Date: |  |

Emergency Contact Number:

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  | Date: |  |
| Corrective Action: |  | Date: |  |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

| Type                            | #   | Comment                    | Corrective Action  | Date  | corrective date |
|---------------------------------|-----|----------------------------|--------------------|-------|-----------------|
| Type: Ancillary equipment       | # 1 | Comment: Blow down muffler | Corrective Action: | Date: |                 |
| Type: Gas Meter Run             | # 1 | Comment:                   | Corrective Action: | Date: |                 |
| Type: Emission Control Device   | # 1 | Comment:                   | Corrective Action: | Date: |                 |
| Type: Vertical Heated Separator | # 7 | Comment:                   | Corrective Action: | Date: |                 |
| Type: Pig Station               | # 1 | Comment:                   | Corrective Action: | Date: |                 |
| Type: Plunger Lift              | # 7 | Comment:                   | Corrective Action: | Date: |                 |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tanak ID | SE GPS                |
|--------------------|---|----------|-----------|----------|-----------------------|
| CONDENSATE         | 2 | 500 BBLS | STEEL AST |          | 39.484573,-107.755137 |
| Comment:           |   |          |           |          |                       |
| Corrective Action: |   |          |           |          | Date:                 |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities  |              |       |      |                       |            |                  |
|-----------------------|--------------|-------|------|-----------------------|------------|------------------|
| Facility ID:          | 277039       | Type: | WELL | API Number: 045-10585 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b> |              |       |      |                       |            |                  |
| Comment:              | Plunger lift |       |      |                       |            |                  |
| Corrective Action:    |              |       |      |                       |            | Date:            |
| Facility ID:          | 277040       | Type: | WELL | API Number: 045-10584 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b> |              |       |      |                       |            |                  |
| Comment:              | Plunger lift |       |      |                       |            |                  |
| Corrective Action:    |              |       |      |                       |            | Date:            |
| Facility ID:          | 277041       | Type: | WELL | API Number: 045-10583 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b> |              |       |      |                       |            |                  |
| Comment:              | Plunger lift |       |      |                       |            |                  |
| Corrective Action:    |              |       |      |                       |            | Date:            |
| Facility ID:          | 277043       | Type: | WELL | API Number: 045-10581 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b> |              |       |      |                       |            |                  |
| Comment:              | Plunger lift |       |      |                       |            |                  |
| Corrective Action:    |              |       |      |                       |            | Date:            |
| Facility ID:          | 277381       | Type: | WELL | API Number: 045-10695 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b> |              |       |      |                       |            |                  |
| Comment:              | Plunger lift |       |      |                       |            |                  |
| Corrective Action:    |              |       |      |                       |            | Date:            |
| Facility ID:          | 277382       | Type: | WELL | API Number: 045-10696 | Status: PR | Insp. Status: PR |
| <b>Producing Well</b> |              |       |      |                       |            |                  |
| Comment:              | Plunger lift |       |      |                       |            |                  |
| Corrective Action:    |              |       |      |                       |            | Date:            |

**Environmental**

**Spill/Remediation:**

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Culverts                | Pass                  |               |                          |         |
|                  |                 | Ditches                 | Pass                  |               |                          |         |
| Ditches          | Pass            |                         |                       |               |                          |         |
|                  |                 | Gravel                  | Pass                  |               |                          |         |
| Berms            | Pass            |                         |                       |               |                          |         |
| Gravel           | Pass            |                         |                       |               |                          |         |
| Seeding          | Pass            |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL                                                                                                                                                                 |
|--------------|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 666802723    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4000040">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4000040</a> |