

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/09/2016

Submitted Date:

11/09/2016

Document Number:

674703321**FIELD INSPECTION FORM**

Loc ID 335574	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED							
2A Doc Num: _____			Findings: 30 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested							
Operator Information: OGCC Operator Number: <u>100185</u> Name of Operator: <u>ENCANA OIL & GAS (USA) INC</u> Address: <u>370 17TH ST STE 1700</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>										
Contact Information:										
<table border="1" style="width:100%"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>Inspections, General</td> <td>970-285-2665</td> <td>cogcc.inspections@encana.com</td> <td>EnCana Inspection email</td> </tr> </table>				Contact Name	Phone	Email	Comment	Inspections, General	970-285-2665	cogcc.inspections@encana.com
Contact Name	Phone	Email	Comment							
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email							

Contact Name	Phone	Email	Comment
Inspections, General	970-285-2665	cogcc.inspections@encana.com	EnCana Inspection email

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282307	WELL	PR	03/28/2007	GW	045-11718	N. PARACHUTE EF12B-22 D27595	PR
282308	WELL	PR	05/09/2008	GW	045-11719	N. PARACHUTE EF05D-22D27 595	PR
282309	WELL	PR	03/28/2007	GW	045-11720	N.PARACHUTE EF11B-22 D27 59	PR
282310	WELL	PR	03/28/2007	GW	045-11721	N. PARACHUTE EF09B-21D27 595	PR
282311	WELL	PR	03/28/2007	GW	045-11722	N.PARACHUTE EF06D-22- D27 59	PR
282312	WELL	PR	05/11/2008	GW	045-11723	N. PARACHUTE EF05B-22D27595	PR
282313	WELL	PR	03/28/2007	GW	045-11724	N. PARACHUTE EF11D-22 -D27 59	PR
282314	WELL	PR	03/28/2007	GW	045-11728	N.PARACHUTE EF06B-22 D27 59	PR
282315	WELL	PR	03/28/2007	GW	045-11729	N.PARACHUTE EF09B-22 D27 59	PR
282316	WELL	PR	03/28/2007	GW	045-11730	N.PARACHUTE EF14B-22 D27 59	PR
282317	WELL	PR	03/28/2007	GW	045-11731	N PARACHUTE EF10B22 D27 595	PR
282318	WELL	PR	03/28/2007	GW	045-11732	N. PARACHUTE EF10D-22 D27 59	PR
282334	WELL	PR	08/12/2008	GW	045-11748	N. PARACHUTE EF14B D27 595	PR
282335	WELL	PR	11/26/2008	GW	045-11747	N.PARACHUTE EF 12B D27 595	PR
282336	WELL	PR	02/01/2014	GW	045-11746	N. PARACHUTE EF13B D27 595	PR
282338	WELL	PR	08/01/2008	GW	045-11745	N. PARACHUTE EF11B D27 595	PR

282339	WELL	PR	12/01/2008	GW	045-11744	N.PARACHUTE EF 16B-28 D27 5	PR
282340	WELL	PR	12/01/2008	GW	045-11743	N. PARACHUTE EF05B D27 595	PR
282545	WELL	PR	12/09/2008	GW	045-11778	N. PARACHUTE EF08D-28 D27 59	PR
282546	WELL	PR	12/05/2008	GW	045-11779	N. PARACHUTE EF05A-27 D27 59	PR
282547	WELL	PR	01/27/2014	GW	045-11780	N. PARACHUTE EF09D-28 D27 59	PR
282556	WELL	PR	02/01/2014	GW	045-11790	N. PARACHUTE EF09B-28 D27 59	PR
282557	WELL	PR	12/05/2008	GW	045-11791	N. PARACHUTE EF13A-27 D27 59	PR
282923	WELL	PR	08/10/2008	GW	045-11866	N. PARACHUTE EF12D D27 595	PR
291335	WELL	PR	07/10/2007	GW	045-14332	N.PARACHUTE EF03B D27 595	PR
291336	WELL	PR	07/10/2007	GW	045-14333	N.PARACHUTE EF04D D27 595	PR
291337	WELL	PR	07/10/2007	GW	045-14334	N.PARACHUTE EF02B D27 595	PR
291338	WELL	PR	07/10/2007	GW	045-14335	N.PARACHUTE EF 15B-22 D27 5	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 800-791-7691

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 20		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 16		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 20		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 5		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 20		
Comment:			

Inspected Facilities									
Facility ID:	282307	Type:	WELL	API Number:	045-11718	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282308	Type:	WELL	API Number:	045-11719	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282309	Type:	WELL	API Number:	045-11720	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282310	Type:	WELL	API Number:	045-11721	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282311	Type:	WELL	API Number:	045-11722	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282312	Type:	WELL	API Number:	045-11723	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282313	Type:	WELL	API Number:	045-11724	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282314	Type:	WELL	API Number:	045-11728	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	282315	Type:	WELL	API Number:	045-11729	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282316	Type:	WELL	API Number:	045-11730	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282317	Type:	WELL	API Number:	045-11731	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282318	Type:	WELL	API Number:	045-11732	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282334	Type:	WELL	API Number:	045-11748	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282335	Type:	WELL	API Number:	045-11747	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282336	Type:	WELL	API Number:	045-11746	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282338	Type:	WELL	API Number:	045-11745	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	282339	Type:	WELL	API Number:	045-11744	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282340	Type:	WELL	API Number:	045-11743	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282545	Type:	WELL	API Number:	045-11778	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282546	Type:	WELL	API Number:	045-11779	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282547	Type:	WELL	API Number:	045-11780	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282556	Type:	WELL	API Number:	045-11790	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282557	Type:	WELL	API Number:	045-11791	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	282923	Type:	WELL	API Number:	045-11866	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	291335	Type:	WELL	API Number:	045-14332	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	291336	Type:	WELL	API Number:	045-14333	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	291337	Type:	WELL	API Number:	045-14334	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Facility ID:	291338	Type:	WELL	API Number:	045-14335	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Check Dams	Pass					
Hydro Mulch	Pass					
Berms	Pass					
Gravel	Pass					
Ditches	Pass					
		Ditches	Pass			
		Culverts	Pass			
		Check Dams	Pass			
Compaction	Pass					
		Gravel	Pass			
		Compaction	Pass			
				Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674703321	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4005122