

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/17/2016

Submitted Date:

11/18/2016

Document Number:

666802733

FIELD INSPECTION FORM

Loc ID 334736 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
 Name of Operator: ENCANA OIL & GAS (USA) INC
 Address: 370 17TH ST STE 1700
 City: DENVER State: CO Zip: 80202-

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291185	WELL	PR	02/29/2008	GW	045-14320	CHEROKEE MOUNTAIN ESTATES 3-14C (N3E)	PR
291187	WELL	PR	02/06/2008	GW	045-14319	CHEROKEE MOUNTAIN ESTATES 3-14D (N3E)	PR
291191	WELL	PR	03/19/2008	GW	045-14318	CHEROKEE MOUNTAIN ESTATES 3-14B (N3E)	PR
292499	WELL	PR	01/31/2008	GW	045-14746	CHEROKEE MOUNTAIN ESTATES 3-15 (N3E)	PR
292501	WELL	PR	02/09/2008	GW	045-14747	CHEROKEE MOUNTIAN ESTATES 10-3 (N3E)	PR
293735	WELL	PR	01/29/2008	GW	045-15124	CHEROKEE MOUNTAIN ESTATES 3-15A (N3E)	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	AIRS ID 045-1762-001		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good:

Spills:

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Vertical Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:


Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	0				
Comment:					
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tanak ID	SE GPS
OTHER	1	OTHER	PLASTIC AST		
Comment: centralized battery					
Corrective Action:				Date:	
Paint					
Condition					
Other (Content)	cahemical unit				
Other (Capacity)	500gal				
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tanak ID	SE GPS
CONDENSATE	2	500 BBLs	STEEL AST		39.471390,-107.654446
Comment:					
Corrective Action:				Date:	
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	



Inspected Facilities									
Facility ID:	291185	Type:	WELL	API Number:	045-14320	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	291187	Type:	WELL	API Number:	045-14319	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	291191	Type:	WELL	API Number:	045-14318	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	292499	Type:	WELL	API Number:	045-14746	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	292501	Type:	WELL	API Number:	045-14747	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	293735	Type:	WELL	API Number:	045-15124	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Rip Rap	Pass			
Gravel	Pass					
Berms	Pass					
		Sediment Traps	Pass			
Seeding	Pass					
		Gravel	Pass			
		Ditches	Pass			
		Culverts	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT