

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/16/2016

Submitted Date:

11/18/2016

Document Number:

666802738**FIELD INSPECTION FORM**

Loc ID 334590 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266186	WELL	PR	07/04/2003	GW	045-09118	ARBANEY 3-16C (P3)	PR
270125	WELL	PR	07/19/2006	GW	045-09463	MAGIC 10-2 (P3)	PR
270126	WELL	PR	07/02/2006	GW	045-09462	MAGIC 10-1(P3)	PR
270127	WELL	PR	07/24/2006	GW	045-09461	MAGIC 10-1A (P3)	PR
270139	WELL	PR	07/19/2006	GW	045-09465	ARBANEY 3-15C (P3)	PR

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:	AIRS ID 045-0655-001		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Blow down muffler		
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		
Comment:	Centralized battery				
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	

Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tanak ID	SE GPS	
CONDENSATE	2	500 BBLs	STEEL AST		39.468913,-107.646626	
Comment:						
Corrective Action:				Date:		
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		
Venting:						
Yes/No	YES					
Comment:	Bradenhead valves open, all are manifolded to pipe system and sent to portable flare stack					
Corrective Action:					Date:	
Flaring:						
Type	Field Flare					
Comment:	Bradenhead Gas					
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 266186	Type: WELL	API Number: 045-09118	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 270125	Type: WELL	API Number: 045-09463	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 270126	Type: WELL	API Number: 045-09462	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 270127	Type: WELL	API Number: 045-09461	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID: 270139	Type: WELL	API Number: 045-09465	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Culverts	Pass			
		Ditches	Pass			
		Gravel	Pass			
Seeding	Pass					
Berms	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT