

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <input type="text"/>				
Corrective Action: <input type="text"/>				Date: <input type="text"/>

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type	<input type="text"/>
Comment:	<input type="text"/>
Corrective Action:	<input type="text"/>
	Date: <input type="text"/>

Inspected Facilities

Facility ID: 211515 Type: WELL API Number: 045-07275 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT