

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/10/2016

Submitted Date:

11/10/2016

Document Number:

674703326

FIELD INSPECTION FORM
 Loc ID 335512 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Janicek, Jake		JJanicek@caerusoilandgas.com	
McKee, Michael		MMckee@caerusoilandgas.com	
Elsener, Garrett		garrett@caerusoilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447167	WELL	DG	11/01/2016		045-23280	Puckett 42D-23	DG

General Comment:

Location Construction

Location ID: 447167 CDP: _____

Comment: _____

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: Notices are being received

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____ Date: _____

Comment: _____

Corrective Action: _____ **Date:** _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected FacilitiesFacility ID: 447167 Type: WELL API Number: 045-23280 Status: DG Insp. Status: DG**Well Drilling**

Rig: Rig Name: H&P 330 Pusher/Rig Manager: Whitey
Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydri Type: _____
Pressure Test BOP: Pass Test Pressure PSI: 3000 Safety Plan: YES

Drill Fluids**Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
Multi-Well: YES Disposal Location: _____

Comment: Drilling production hole. @ 3989' coming out of hole to pick up directional tools.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	
Compaction	Pass	Compaction	Pass			
				Covering Materials	Pass	
Berms	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674703326	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4000928