



Photo#1: View of Location from Entry Road to North

November 3, 2016

Inspection Photos: Laramie David Location #334500



Photo#2: Interim Vegetation area at South side of Location.

November 3, 2016

Inspection Photos: Laramie David Location #334500



Photo#3: Rock Drain and Wattles at east end of Location

November 3, 2016

Inspection Photos: Laramie David Location #334500



Photo#4: Guy Anchor; smashed and Marker broken off.

November 3, 2016

Inspection Photos: Laramie David Location #334500