



Photo#1: Overview of Location from Entry to West

November 3, 2016

Inspection Photos: Laramie McElwain Location #334506



Photo#2: Interim Vegetation is well established.

November 3, 2016

Inspection Photos: Laramie McElwain Location #334506



Photo#3: Rocked Drain at SE Corner of Location.

November 3, 2016

Inspection Photos: Laramie McElwain Location #334506