

Final Reclamation Inspection



Photo 1. Photo taken west of location, facing East. Follow up inspection indicates location has not been reclaimed.

Final Reclamation Inspection



Photo 2. Photo taken north of location, facing South. Follow up inspection indicates location has not been reclaimed.

Final Reclamation Inspection



Photo 3. Photo taken from well location indicating the presence of a List B Colorado noxious weed Canada thistle (*Cirsium arvense*).