

Final Reclamation Inspection



Photo 1. Photo taken south of location, facing Northwest. Does not appear the well was constructed at the proposed location based off field observations.

Final Reclamation Inspection



Photo 2. Photo taken south of location, facing Northeast. Does not appear the well was constructed at the proposed location based off field observations.