

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/10/2016

Submitted Date:

11/15/2016

Document Number:

672500162**FIELD INSPECTION FORM**

Loc ID 336611 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250671	WELL	PR	10/21/2009	GW	123-18474	UPV 27-8H6	PA

General Comment:

Inspected FacilitiesFacility ID: 250671 Type: WELL API Number: 123-18474 Status: PR Insp. Status: PA**Cement**Cement ContractorContractor Name: LEED

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: YESCement Type: G-NeatComment:

CREW TO LOCATION. IWP 0. OPEN WELL T WORK TANK. TEST RIG BRAKES & INSPECT ELEVATORS. PU & RIH W/ 80 JTS 2 1/16" CSH. BOT @ 2520.73'. LOAD WELL BORE & ESTABLISH CIRCULATION. CONDITION FOR APPROX 15MIN. KILL PUMP. MIRU LEED CMT. HOLD SFTY MTG. PRIME & TEST LINES TO 2500PSI. BLEED OFF. PUMP 3BBL TO ESTABLISH CIRCULATION THEN MIX & PUMP 100SX 15.8# G-NEAT CMT (20.5BBL). RD LEED CMT. POOH LD ON FLOAT W/ 62 JTS 2 1/16" TBG, LEAVING 18 JTS 2 1/16" W/ BOT @ 573.86'. RU LEED CMT. PUMP 4BBL TO ESTABLISH CIRCULATION THEN MIX & PUMP 206SX 15.8# G-NEAT CMT (42.1BBL) UNTIL CMT TO SURFACE. PUMP 1/2BBL FRESH WATER TO CLEAR LINES. THEN RD LEED CMT. POOH LD ON FLOAT W/ 18 JTS 2 1/16" TBG. ND BOPS. ND P&A SPOOL. RU LEED CMT & TOP WELL OF W/ 2BBL CMT SLURRY. RDMO LEED CMT. NU NIGHT CAP ON SC. SHUT WELL IN. CLEAN LOCATION. RDMO.

STUB PLUG: 80 JTS TBG W/ BOT @ 2520'. 100SX CMT (20.5BBL)
FROM: 2291'-2520'

SHOE PLUG: 18 JTS TBG W/ BOT @ 573'. 206SX CMT (42.1BBL)
FROM: 573'-SURFACE

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
672500162	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4003073