



**photo 1:** Center of the location facing north.



**photo 2:** Center of the location facing west.





**photo 3:** Center of the location facing south.



**photo 4:** Center of the location facing east.





**photo 5:** Facing east at the location.



**photo 6:** There are areas with no vegetation establishment.





**photo 7:** There is tall weed debris (kochia) throughout the location.



**photo 8:** Facing south toward the surrounding undisturbed pasture.