

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/18/2016

Submitted Date:

11/18/2016

Document Number:

666802739

FIELD INSPECTION FORM

Loc ID 334909 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
 Name of Operator: ENCANA OIL & GAS (USA) INC
 Address: 370 17TH ST STE 1700
 City: DENVER State: CO Zip: 80202-

Findings:

13 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270706	WELL	PR	06/17/2009	GW	045-09787	BROWN 11-2C (F11E)	PR
293456	WELL	PR	05/30/2009	GW	045-14999	ENCANA 11-3B2 (F11E)	PR
294723	WELL	PR	06/03/2009	GW	045-15578	ENCANA 11-5(F11E)	PR
294724	WELL	PR	06/07/2009	GW	045-15579	ENCANA 11-4C(F11E)	PR
294725	WELL	PR	06/05/2009	GW	045-15580	ENCANA 11-12A (F11E)	PR
294726	WELL	PR	05/31/2009	GW	045-15581	ENCANA 11-4D (F11E)	PR
299256	WELL	PR	06/11/2009	GW	045-17627	ENCANA FEDERAL 11-11A (F11E)	PR
299516	WELL	PR	05/25/2009	GW	045-17698	ENCANA 11-6(F11E)	PR
299517	WELL	PR	05/28/2009	GW	045-17699	ENCANA 11-6A(F11E)	PR
299518	WELL	PR	05/21/2009	GW	045-17700	ENCANA 11-3D(F11E)	PR

General Comment:

Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tanak ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST			
Comment: Centralized battery						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tanak ID	SE GPS	
CONDENSATE	2	500 BBLs	STEEL AST		39.463918,-107.637901	
Comment:						
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						

Comment:		
Corrective Action:	Date:	

--

Inspected Facilities									
Facility ID:	270706	Type:	WELL	API Number:	045-09787	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	293456	Type:	WELL	API Number:	045-14999	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	294723	Type:	WELL	API Number:	045-15578	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	294724	Type:	WELL	API Number:	045-15579	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	294725	Type:	WELL	API Number:	045-15580	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	294726	Type:	WELL	API Number:	045-15581	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	299256	Type:	WELL	API Number:	045-17627	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	299516	Type:	WELL	API Number:	045-17698	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				

Facility ID: 299517 Type: WELL API Number: 045-17699 Status: PR Insp. Status: PR

Producing Well

Comment: Plunger lift

Corrective Action:

Date:

Facility ID: 299518 Type: WELL API Number: 045-17700 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In

Temporarily Abandoned

Reminder: _____

Comment: Last production numbers posted Sept 2016

Corrective Action:

Date: _____

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
		Ditches	Pass			
Gravel	Pass					
Berms	Pass					
Seeding	Pass					
Ditches	Pass					
		Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666802739	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007240