

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/21/2016

Submitted Date:

11/21/2016

Document Number:

674703375**FIELD INSPECTION FORM**
 Loc ID 335343 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name          | Phone        | Email                              | Comment |
|-----------------------|--------------|------------------------------------|---------|
| Inspection, Terra TEP | 970-263-2716 | COGCCInspectionReports@terraep.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 210780      | WELL | PR     | 09/02/1987  | GW         | 045-06538 | MOBIL W-19-28 | PR          |
| 263953      | WELL | PR     | 09/22/2002  | GW         | 045-08164 | PA 34-28      | PR          |
| 263954      | WELL | PR     | 09/22/2002  | GW         | 045-08165 | PA 334-28     | PR          |
| 271283      | WELL | PR     | 06/27/2004  | GW         | 045-09860 | PA 434-28     | PR          |
| 271288      | WELL | PR     | 06/29/2004  | GW         | 045-09857 | PA 534-28     | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | CONTAINERS           |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

|                    |              |       |  |
|--------------------|--------------|-------|--|
| <b>Fencing/:</b>   |              |       |  |
| Type               | WELLHEAD     |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | TANK BATTERY |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |
| Type               | SEPARATOR    |       |  |
| Comment:           |              |       |  |
| Corrective Action: |              | Date: |  |

|                                   |                             |       |                 |
|-----------------------------------|-----------------------------|-------|-----------------|
| <b>Equipment:</b>                 |                             |       | corrective date |
| Type: Ancillary equipment         | # 1                         |       |                 |
| Comment:                          | Chemical container at wells |       |                 |
| Corrective Action:                |                             | Date: |                 |
| Type: Horizontal Heated Separator | # 4                         |       |                 |

|                       |     |  |       |
|-----------------------|-----|--|-------|
| Comment:              |     |  |       |
| Corrective Action:    |     |  | Date: |
| Type: Plunger Lift    | # 4 |  |       |
| Comment:              |     |  |       |
| Corrective Action:    |     |  | Date: |
| Type: Gas Meter Run   | # 1 |  |       |
| Comment:              |     |  |       |
| Corrective Action:    |     |  | Date: |
| Type: Bird Protectors | # 2 |  |       |
| Comment:              |     |  |       |
| Corrective Action:    |     |  | Date: |

**Tanks and Berms:**

|                    |   |           |           |          |        |       |
|--------------------|---|-----------|-----------|----------|--------|-------|
| Contents           | # | Capacity  | Type      | Tanak ID | SE GPS |       |
| PRODUCED WATER     | 2 | <100 BBLs | STEEL AST |          | ,      |       |
| Comment:           |   |           |           |          |        |       |
| Corrective Action: |   |           |           |          |        | Date: |

**Paint**

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) | 80 bbl   |  |
| Other (Type)     |          |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Type               |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Inspected Facilities**

|                     |            |                       |            |                  |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 210780 | Type: WELL | API Number: 045-06538 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

|                     |            |                       |            |                  |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 263953 | Type: WELL | API Number: 045-08164 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

|                     |            |                       |            |                  |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 263954 | Type: WELL | API Number: 045-08165 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

|                     |            |                       |            |                  |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 271283 | Type: WELL | API Number: 045-09860 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

|                     |            |                       |            |                  |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 271288 | Type: WELL | API Number: 045-09857 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

**Producing Well**

Comment: Producing well

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
|                  |                 | Ditches                 | Pass                  |  |                          |         |
|                  |                 | Gravel                  | Pass                  |  |                          |         |
| Berms            | Pass            |                         |                       |  |                          |         |
|                  |                 | Compaction              | Pass                  |  |                          |         |
|                  |                 | Culverts                | Pass                  |  |                          |         |
| Gravel           | Pass            |                         |                       |  |                          |         |
| Ditches          | Pass            |                         |                       |  |                          |         |
|                  |                 |                         |                       | Material Handling And Spill Prevention | Pass                     |         |
| Compaction       | Pass            |                         |                       |  |                          |         |
| Seeding          | Pass            |                         |                       |  |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 674703375    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4008445">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4008445</a> |