

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/18/2016

Submitted Date:

11/18/2016

Document Number:

675203625**FIELD INSPECTION FORM**
 Loc ID 334653 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Encana,		cogcc.inspections@encana.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270427	WELL	PR	01/01/2005	GW	045-09558	CLEM 15-13	PR
298053	WELL	PR	07/18/2009	GW	045-17045	CLEM JR. 15-7BB(PB-15)	PR
298056	WELL	PR	07/14/2009	GW	045-17046	CLEM JR. 15-3(PB-15)	PR
298060	WELL	PR	07/05/2009	GW	045-17047	CLEM JR. 15-6 (PB-15)	PR
298061	WELL	PR	07/09/2009	GW	045-17048	CLEM JR. 15-6BB(PB-15)	PR
298062	WELL	PR	07/14/2009	GW	045-17049	CLEM JR. 15-2BB(PB-15)	PR
298393	WELL	PR	08/09/2009	GW	045-17181	CLEM JR. 15-8 (PB-15)	PR
298394	WELL	PR	08/07/2009	GW	045-17180	CLEM JR. 15-7(PB-15)	PR
298395	WELL	PR	08/12/2009	GW	045-17179	CLEM JR. 15-1BB (PB-15)	PR
298711	WELL	PR	07/02/2009	GW	045-17378	CLEM JR. 15-3BB(PB-15)	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST		,	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>

Paint

Condition	Adequate	<input type="text"/>
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date: <input type="text"/>

Contents	#	Capacity	Type	Tanak ID	SE GPS	
CONDENSATE	4	300 BBLS	STEEL AST		,	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date: <input type="text"/>	

Paint

Condition	Adequate	<input type="text"/>
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	<input type="text"/>				

Inspected Facilities				
Facility ID: <u>270427</u>	Type: <u>WELL</u>	API Number: <u>045-09558</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298053</u>	Type: <u>WELL</u>	API Number: <u>045-17045</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298056</u>	Type: <u>WELL</u>	API Number: <u>045-17046</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298060</u>	Type: <u>WELL</u>	API Number: <u>045-17047</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298061</u>	Type: <u>WELL</u>	API Number: <u>045-17048</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298062</u>	Type: <u>WELL</u>	API Number: <u>045-17049</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298393</u>	Type: <u>WELL</u>	API Number: <u>045-17181</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298394</u>	Type: <u>WELL</u>	API Number: <u>045-17180</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298395</u>	Type: <u>WELL</u>	API Number: <u>045-17179</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>298711</u>	Type: <u>WELL</u>	API Number: <u>045-17378</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Gravel	Pass					
Compaction	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203625	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4007256