

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/21/2016

Submitted Date:

11/21/2016

Document Number:

675203631**FIELD INSPECTION FORM**
 Loc ID 335026 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	<a href="#">Petroleum Engineer</a>
Encana,		cogcc.inspections@encana.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295110	WELL	PR	02/01/2011	GW	045-15649	FEDERAL BOSELY 16-2BB (PH-16)	PR
295140	WELL	PR	12/04/2008	GW	045-15667	FEDERAL 15-5 (PH-16)	PR
295141	WELL	PR	11/08/2008	GW	045-15668	FEDERAL 16-1 (PH-16)	PR
295142	WELL	PR	12/15/2008	GW	045-15669	FEDERAL 16-8 (PH-16)	PR
295143	WELL	PR	12/21/2008	GW	045-15670	FEDERAL 16-8BB (PH-16)	PR
295144	WELL	PR	12/21/2008	GW	045-15671	FEDERAL 15-5BB(PH16)	PR
295145	WELL	PR	08/14/2009	GW	045-15673	FEDERAL 15-4 (PH-16)	PR
295146	WELL	PR	12/21/2008	GW	045-15674	FEDERAL BOSELY 16-2 (PH-16)	PR
295147	WELL	PR	11/18/2008	GW	045-15675	FEDERAL 16-1BB (PH-16)	PR
295187	WELL	PR	02/01/2011	GW	045-15672	FEDERAL 15-4BB (PH-16)	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST		,	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>

**Paint**

Condition	Adequate	<input type="text"/>
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date: <input type="text"/>

Contents	#	Capacity	Type	Tanak ID	SE GPS	
CONDENSATE	4	300 BBLS	STEEL AST		,	
Comment:	One tank labeled permanently closed					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>

**Paint**

Condition	Adequate	<input type="text"/>
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	<input type="text"/>				

Corrective Action:		Date:	
--------------------	--	-------	--

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

--	--	--

Inspected Facilities									
Facility ID:	<u>295110</u>	Type:	<u>WELL</u>	API Number:	<u>045-15649</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295140</u>	Type:	<u>WELL</u>	API Number:	<u>045-15667</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295141</u>	Type:	<u>WELL</u>	API Number:	<u>045-15668</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295142</u>	Type:	<u>WELL</u>	API Number:	<u>045-15669</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295143</u>	Type:	<u>WELL</u>	API Number:	<u>045-15670</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295144</u>	Type:	<u>WELL</u>	API Number:	<u>045-15671</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295145</u>	Type:	<u>WELL</u>	API Number:	<u>045-15673</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295146</u>	Type:	<u>WELL</u>	API Number:	<u>045-15674</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295147</u>	Type:	<u>WELL</u>	API Number:	<u>045-15675</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295187</u>	Type:	<u>WELL</u>	API Number:	<u>045-15672</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Retention Ponds	Pass					
Compaction	Pass	Gravel	Pass			
Gravel	Pass					
Berms	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203631	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4008150">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4008150</a>