

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/21/2016

Submitted Date:

11/21/2016

Document Number:

675203636**FIELD INSPECTION FORM**

Loc ID 334761	Inspector Name: CONKLIN, CURTIS	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>100185</u> Name of Operator: <u>ENCANA OIL & GAS (USA) INC</u> Address: <u>370 17TH ST STE 1700</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>				Findings: 1 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Encana,		cogcc.inspections@encana.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286065	WELL	PR	02/18/2008	GW	045-12604	ENYEART 16-4 (PD16)	PR
288790	WELL	PR	02/11/2008	GW	045-13575	ENYEART 16-4BB(PD16)	PR
288793	WELL	PR	02/14/2008	GW	045-13574	ENYEART 16-5BB(PD16)	PR
288799	WELL	PR	02/08/2008	GW	045-13573	ENYEART 16-5(PD16)	PR
300667	WELL	PR	05/05/2011	GW	045-17968	ENYEART GARDNER 16-5D (PD16)	PR
300668	WELL	PR	10/07/2010	GW	045-17969	ENYEART 17-8C (PD16)	PR
300669	WELL	PR	05/27/2010	GW	045-17970	ENYEART PAVISICH 16-3C (PD16)	PR
300670	WELL	PR	05/12/2010	GW	045-17971	ENYEART 17-1C (PD 16)	PR
300671	WELL	PR	05/22/2010	GW	045-17972	ENYEART 16-4D (PD16)	PR
300672	WELL	PR	05/23/2010	GW	045-17973	ENYEART 16-4C(PD16)	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tanak ID	SE GPS	
METHANOL	1	<50 BBLS	STEEL AST		,	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>

Paint

Condition	Adequate	<input type="text"/>
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date: <input type="text"/>

Contents	#	Capacity	Type	Tanak ID	SE GPS	
CONDENSATE	7	300 BBLS	STEEL AST		,	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date: <input type="text"/>	

Paint

Condition	Adequate	<input type="text"/>
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	<input type="text"/>				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--	--

Inspected Facilities				
Facility ID: <u>286065</u>	Type: <u>WELL</u>	API Number: <u>045-12604</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>288790</u>	Type: <u>WELL</u>	API Number: <u>045-13575</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>288793</u>	Type: <u>WELL</u>	API Number: <u>045-13574</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>288799</u>	Type: <u>WELL</u>	API Number: <u>045-13573</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>300667</u>	Type: <u>WELL</u>	API Number: <u>045-17968</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>300668</u>	Type: <u>WELL</u>	API Number: <u>045-17969</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>300669</u>	Type: <u>WELL</u>	API Number: <u>045-17970</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>300670</u>	Type: <u>WELL</u>	API Number: <u>045-17971</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>300671</u>	Type: <u>WELL</u>	API Number: <u>045-17972</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>300672</u>	Type: <u>WELL</u>	API Number: <u>045-17973</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			
Retention Ponds	Pass					
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203636	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4008175