

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
11/18/2016
Submitted Date:
11/18/2016
Document Number:
674703361

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
323789 _____ LONGWORTH, MIKE _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Findings:

21 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-263-2716	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210810	WELL	PR	06/22/1998	GW	045-06568	MOBIL MV-29-27	PR
418043	WELL	PR	04/16/2011	GW	045-19659	ExxonMobil GM 433-27	PR
418044	WELL	PR	04/16/2011	GW	045-19660	ExxonMobil GM 23-26	PR
418045	WELL	PR	09/21/2011	GW	045-19661	ExxonMobil GM 313-26	PR
418046	WELL	PR	10/01/2011	GW	045-19662	ExxonMobil GM 14-26	PR
418047	WELL	PR	11/12/2011	GW	045-19663	ExxonMobil GM 514-26	PR
418048	WELL	PR	01/17/2012	GW	045-19664	ExxonMobil GM 443-27	PR
418049	WELL	PR	07/31/2011	GW	045-19665	ExxonMobil GM 44-27	PR
418050	WELL	PR	04/16/2011	GW	045-19666	ExxonMobil GM 343-27	PR
418051	WELL	PR	10/30/2011	GW	045-19667	ExxonMobil GM 444-27	PR
418052	WELL	PR	09/21/2011	GW	045-19668	ExxonMobil GM 314-26	PR
418053	WELL	PR	10/18/2011	GW	045-19669	ExxonMobil GM 344-27	PR
418054	WELL	PR	09/21/2011	GW	045-19670	ExxonMobil GM 533-27	PR
418055	WELL	PR	04/16/2011	GW	045-19671	ExxonMobil GM 323-26	PR
418056	WELL	PR	10/01/2011	GW	045-19672	ExxonMobil GM 423-26	PR
418057	WELL	PR	09/21/2011	GW	045-19673	ExxonMobil GM 414-26	PR
418058	WELL	PR	06/17/2011	GW	045-19674	ExxonMobil GM 13-26	PR
418374	WELL	PR	09/21/2011	GW	045-19695	ExxonMobil GM 544-27	PR

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Tank volumes written in are unreadable from out side of berm.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	970-285-9377		
Corrective Action:		Date:	_____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 12		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		

Comment: Containers at wells			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 20		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 18		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	210810	Type:	WELL	API Number:	045-06568	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	418043	Type:	WELL	API Number:	045-19659	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	418044	Type:	WELL	API Number:	045-19660	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	418045	Type:	WELL	API Number:	045-19661	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	418046	Type:	WELL	API Number:	045-19662	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	418047	Type:	WELL	API Number:	045-19663	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	418048	Type:	WELL	API Number:	045-19664	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				
Facility ID:	418049	Type:	WELL	API Number:	045-19665	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:					Date:				

Facility ID: 418050	Type: WELL	API Number: 045-19666	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 418051	Type: WELL	API Number: 045-19667	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 418052	Type: WELL	API Number: 045-19668	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 418053	Type: WELL	API Number: 045-19669	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 418054	Type: WELL	API Number: 045-19670	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 418055	Type: WELL	API Number: 045-19671	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 418056	Type: WELL	API Number: 045-19672	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:
Facility ID: 418057	Type: WELL	API Number: 045-19673	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:				Date:

Facility ID: 418058 Type: WELL API Number: 045-19674 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 418374 Type: WELL API Number: 045-19695 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Gravel	Pass			
				Material Handling And Spill Prevention	Pass	
Gravel	Pass					
Ditches	Pass					
Compaction	Pass					
		Culverts	Pass			
		Compaction	Pass			
Seeding	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674703361	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4012084