

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/21/2016

Submitted Date:

11/21/2016

Document Number:

675203633**FIELD INSPECTION FORM**

Loc ID 432551	Inspector Name: CONKLIN, CURTIS	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>100185</u> Name of Operator: <u>ENCANA OIL & GAS (USA) INC</u> Address: <u>370 17TH ST STE 1700</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>				Findings: 1 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Encana,		cogcc.inspections@encana.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432292	WELL	PR	12/31/2013	GW	045-21945	Hagen Federal 22-1AA (PC22)	PR
432546	WELL	PR	01/06/2014	GW	045-22005	Hagen Federal 15-16C (PC22)	PR
432547	WELL	PR	12/31/2013	GW	045-22006	Hagen Federal 22-4C (PC22)	PR
432548	WELL	PR	12/25/2013	GW	045-22007	Hagen Federal 22-1D (PC22)	PR
432549	WELL	PR	01/07/2014	GW	045-22008	Hagen Federal 22-4B (PC22)	PR
432550	WELL	PR	04/03/2014	GW	045-22009	Hagen Federal 15-16B (PC22)	PR
432552	WELL	PR	01/10/2014	GW	045-22010	Hagen Federal 22-8A (PC22)	PR
432553	WELL	PR	12/19/2013	GW	045-22011	Hagen Federal 22-5A (PC22)	PR
432554	WELL	PR	01/13/2014	GW	045-22012	Hagen Federal 22-2DD (PC22)	PR
432555	WELL	PR	12/27/2013	GW	045-22013	Hagen Federal 22-4D (PC22)	PR
432556	WELL	PR	01/18/2014	GW	045-22014	Hagen Federal 22-5AA (PC22)	PR
432557	WELL	PR	12/31/2013	GW	045-22015	Hagen Federal 22-2D (PC22)	PR
432558	WELL	PR	01/17/2014	GW	045-22016	Hagen Federal 22-1A (PC22)	PR
432561	WELL	PR	12/31/2013	GW	045-22017	Hagen 22-3B (PC22)	PR
432562	WELL	PR	01/10/2014	GW	045-22018	Hagen 15-13D (PC22)	PR
432563	WELL	PR	01/16/2014	GW	045-22019	Hagen 15-14A (PC22)	PR
432564	WELL	PR	01/14/2014	GW	045-22020	Hagen 22-3D (PC22)	PR
432565	WELL	PR	01/11/2014	GW	045-22021	Hagen 15-14C (PC22)	PR

432566	WELL	PR	01/18/2014	GW	045-22022	Hagen 15-14D (PC22)	PR
432567	WELL	PR	01/10/2014	GW	045-22023	Hagen 22-3A (PC22)	PR
432810	WELL	PR	01/13/2014	GW	045-22050	Hagen Clem 15-10C (PC22)	PR

General Comment:

Inspected Facilities				
Facility ID: <u>432292</u>	Type: <u>WELL</u>	API Number: <u>045-21945</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>432546</u>	Type: <u>WELL</u>	API Number: <u>045-22005</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>432547</u>	Type: <u>WELL</u>	API Number: <u>045-22006</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>432548</u>	Type: <u>WELL</u>	API Number: <u>045-22007</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>432549</u>	Type: <u>WELL</u>	API Number: <u>045-22008</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>432550</u>	Type: <u>WELL</u>	API Number: <u>045-22009</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>432552</u>	Type: <u>WELL</u>	API Number: <u>045-22010</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>432553</u>	Type: <u>WELL</u>	API Number: <u>045-22011</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>432554</u>	Type: <u>WELL</u>	API Number: <u>045-22012</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>432555</u>	Type: <u>WELL</u>	API Number: <u>045-22013</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>432556</u>	Type: <u>WELL</u>	API Number: <u>045-22014</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>432557</u>	Type: <u>WELL</u>	API Number: <u>045-22015</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>432558</u>	Type: <u>WELL</u>	API Number: <u>045-22016</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>432561</u>	Type: <u>WELL</u>	API Number: <u>045-22017</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>432562</u>	Type: <u>WELL</u>	API Number: <u>045-22018</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>432563</u>	Type: <u>WELL</u>	API Number: <u>045-22019</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>432564</u>	Type: <u>WELL</u>	API Number: <u>045-22020</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>432565</u>	Type: <u>WELL</u>	API Number: <u>045-22021</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>432566</u>	Type: <u>WELL</u>	API Number: <u>045-22022</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Facility ID:	432567	Type:	WELL	API Number:	045-22023	Status:	PR	Insp. Status:	PR
Facility ID:	432810	Type:	WELL	API Number:	045-22050	Status:	PR	Insp. Status:	PR

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			
Gravel	Pass	Culverts	Pass			
Retention Ponds	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675203633	INSPECTION APPROVED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4012168