

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/17/2016

Submitted Date:

11/17/2016

Document Number:

679902042**FIELD INSPECTION FORM**

Loc ID 303952 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 16000 DALLAS PARKWAY #875City: DALLAS State: TX Zip: 75248-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|----------------------|---------------------------------|---------|
| Grant, Rachael | 918-585-1650 ext 212 | regulatory@foundationenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 253837 | WELL | PR | 07/03/1995 | GW | 125-07715 | LIPPERT 11-30 | PR |

General Comment:

Location

| | | | |
|--------------------|-----------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Gravel road through pasture | | |
| Corrective Action | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|-----------------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Lease sign mounted to fence | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Metal sign by water tank | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|--|-------|--|
| Fencing/: | | | |
| Type | LOCATION | | |
| Comment: | Pipe fence around unit, wellhead, VGS, meter shed and water tank | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Vertical Separator | # 1 | | |
| Comment: | Vertical gas separator 50% buried by meter shed | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Electric panel | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric motor | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|-------------|-------|--|
| Type: Pump Jack | # 1 | | |
| Comment: | Jensen unit | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|--|----------|----------|----------|-----------------------|--|
| Contents | # | Capacity | Type | Tanak ID | SE GPS | |
| PRODUCED WATER | 1 | OTHER | Open Top | | 39.686030,-102.232190 | |
| Comment: | Fiberglass open top water tank 50% buried w/Adequate wildlife screen | | | | | |
| Corrective Action: | | Date: | | | | |

Paint

| | | |
|------------------|---------|--|
| Condition | | |
| Other (Content) | | |
| Other (Capacity) | 210bbls | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|--|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | Date: | | | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 253837 | Type: | WELL | API Number: | 125-07715 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. Casing production | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |
| Gravel | Pass | Gravel | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 679902042 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4012205 |