

Reclamation Inspection- Overview



Google Earth aerial photo taken 9/7/16 illustrating total disturbance of the Lazy D ZN #03-09 well location. Total area of 4.0 acres (Position dilution of precision (PDOP)= 2.8) was mapped using a Trimble Juno 3B handheld device indicates the location was overbuilt by approximately 0.6 acres.

*1 = Possible topsoil stockpile. Stockpile not marked or documented.

Reclamation Inspection



Photo 1. Photo taken from the northern location, facing Northwest, towards the northern topsoil stockpile.

*1 = Possible topsoil stockpile. Stockpile not marked or documented.

Reclamation Inspection



Photo 2. Photo taken from the northern topsoil stockpile, facing West. Along the center (i.e., top) and south-facing side, vegetation either lacks or an undesirable, weedy annual plant species has established on the stockpile (e.g., Russian thistle) which is not protective of soils to prevent weed establishment under Rule 1002.c.

Reclamation Inspection



Photo 3. Photo taken from the northern topsoil stockpile, facing East. Along the center (i.e., top) and south-facing side, vegetation either lacks or an undesirable, weedy annual plant species has established on the stockpile (e.g., Russian thistle) which is not protective of soils to prevent weed establishment under Rule 1002.c.

Reclamation Inspection



Photo 4. Photo taken from the southern topsoil stockpile, facing West. Portions along the stockpile either lack vegetative growth or an undesirable, weedy annual plant species has established on the stockpile (e.g., Russian thistle) which is not protective of soils to prevent weed establishment under Rule 1002.c.

*1 = Possible topsoil stockpile. Stockpile not marked or documented.

Reclamation Inspection



Photo 5. Photo taken from the northern topsoil stockpile, facing Southeast, illustrating total extent of well location, including areas that have not been reclaimed per Rule 1003.

Reclamation Inspection



Photo 6. Photo taken from the northern topsoil stockpile, facing South, illustrating total extent of well location, including areas that have not been reclaimed per Rule 1003.

Reclamation Inspection



Photo 7. Photo taken from the northern topsoil stockpile, facing Southwest, illustrating total extent of well location, including areas that have not been reclaimed per Rule 1003. .