

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
11/28/2016
Submitted Date:
11/28/2016
Document Number:
674703388

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
324116 _____ LONGWORTH, MIKE _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-263-2716	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257582	WELL	PR	07/10/2000	GW	045-07576	BARRETT GM 21-1	PR

General Comment:

(This area is intentionally left blank for general comments.)

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Dehydrator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		

Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tanak ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities

Facility ID: 257582 Type: WELL API Number: 045-07576 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Culverts	Pass			
		Ditches	Pass			
Seeding	Pass					
		Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT