

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
11/22/2016
Submitted Date:
11/28/2016
Document Number:
680301397

FIELD INSPECTION FORM

Loc ID 312290 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10330
Name of Operator: INVESTMENT EQUIPMENT LLC
Address: 412 W PLATTE AVE
City: FT MORGAN State: CO Zip: 80701

Findings:

4 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Rebol, Dave		daverebol@hotmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221073	WELL	PR	04/05/2016	GW	075-09199	CEDAR CREEK RANCH 1	PA

General Comment:

P&A Inspection - Day (5). Opened well, ran 13 1/2 jts, tagged @ 405', laid down (8) jts., left (5) jts. in hole @ 155' - established circulation to surface. Shut down pump, laid down (5) jts. N.D.B.O.P , topped off well w/cement, wait on cement to tag. Shut down for day. FIR relates to P&A inspection only.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action: **ECN Satisfactory**

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 0		
Comment: No change in surface equipment inventoried			
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 221073 Type: WELL API Number: 075-09199 Status: PR Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Bohler Well Service

Contractor Phone: 970-522-3078

Surface Casing

Cement Volume (sx): 60+50

Circulate to Surface: YES

Cement Fall Back: YES

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): 2

Good Return During Job: YES

Plugging Operations

Depth Plugs(feet range): 4808.32',660',405'

Cement Volume (sx): 2+60+50

Good Return During Job: YES

Cement Type: 15.3#

Comment: See comments pg. 1 for details. Tagged @ 405', good circulation to surface, topped off well, wait on cement to tag. Shut down for day.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Other	In Process			

Comment: [Use BMP's for stormwater erosion control and management](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT