

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
11/23/2016
Submitted Date:
11/28/2016
Document Number:
680301412

FIELD INSPECTION FORM

Loc ID 312290 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10330
Name of Operator: INVESTMENT EQUIPMENT LLC
Address: 412 W PLATTE AVE
City: FT MORGAN State: CO Zip: 80701

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Rebol, Dave		daverebol@hotmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221073	WELL	PR	04/05/2016	GW	075-09199	CEDAR CREEK RANCH 1	PA

General Comment:

P&A Inspection in process. Day (6), Tagged cement @ 53', mixed 10 sks (15.3#), topped off well to surface. Hooked up to flow-line, pumped down (10) bbls. to flush flowline. Contractor will contact F.I. Schure when conditions allow welder to cut off below (4)', weld on cap w/logistics. P&A SATISFACTORY - Flow-line purged SATISFACTORY - FIR related to P&A inspection only, any corrective actions from previous FIR remain in effect.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action: **ECN SATISFACTORY**

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 0		
Comment: No change in surface equipment inventoried			
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 221073 Type: WELL API Number: 075-09199 Status: PR Insp. Status: PA

Cement

Cement Contractor

Contractor Name: Bohler Well Service

Contractor Phone: 970-522-3078

Surface Casing

Cement Volume (sx): 50, 10

Circulate to Surface: YES

Cement Fall Back: NO

Top Job, 1" Volume: YES

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): 2, 60

Good Return During Job: YES

Plugging Operations

Depth Plugs(feet range): 4804,660,405,53

Cement Volume (sx): 2+60+50+10

Good Return During Job: YES

Cement Type: 15.4#

Comment: P&A SATISFACTORY - Cement brought to surface - topped off. Flow-line purged, pumped (10) bbls. to flush. Operator/Contractor will contact F.I. Schure when pipe is cut off below (4)' - cap welded on w/logistics and ready to back-fill. See comments pg. 1 for details of Day (6) P&A.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Other	In Process			

Comment: [Use BMP's for stormwater erosion control and management](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT