

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/23/2016

Submitted Date:

11/28/2016

Document Number:

685301849**FIELD INSPECTION FORM**
 Loc ID 313482 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 1375Name of Operator: LINDE INCAddress: 575 MOUNTAIN AVECity: MURRAY HILL State: NJ Zip: 07974**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hughes, Jerrod	970-565-7021	jerrod.hughes@linde.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
112977	PIT	AC	09/23/1999		-	SCHMIDT 2	AC
224191	WELL	PR	11/30/2007	GW	083-06256	SCHMIDT 2	PR

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		
	Date:	<input type="text"/>	

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Steel Post and Pole		
Corrective Action:		Date:	
Type	PIT		
Comment:	Post and Wire		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Telemetry Equipment		
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Propane Tank		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:		Date:	

Type: Dehydrator	# 2		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Electrical Equipment		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: VRT	# 2		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:	Combuster		
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	112977	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	AC
Facility ID:	224191	Type:	WELL	API Number:	083-06256	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:					Date:				

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? PassProduction areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Compaction	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: YESPit ID: 112977Lat: 37.365448Long: -108.788547

Reference Point: \_\_\_\_\_

Other: \_\_\_\_\_

Length: \_\_\_\_\_

Width: \_\_\_\_\_

**Lining:**

Liner Type:

Liner Condition: Adequate

Comment:

Corrective Action

Date: c**Fencing:**Fencing Type: OtherFencing Condition: Adequate

Comment:

Post and Wire

Corrective Action

Date:

**Netting:**Netting Type: MeshNetting Condition: Good

Comment:

Corrective Action

Date:

Anchor Trench Present: YESOil Accumulation: NO

2+ feet Freeboard:

Comment:

Corrective Action

Date: