

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/21/2016

Submitted Date:

11/22/2016

Document Number:

673714463

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
448313 _____ Sherman, Susan _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 35080
 Name of Operator: GRAND MESA OPERATING CO
 Address: 1700 N. WATERFRONT PKWY BL 600
 City: WICHITA State: KS Zip: 67206

Findings:

- 8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Brewer, Phyllis	(316) 265-3000	pbrewer@gmocks.com	Designated Agent
Reilly, Michael	(316) 265-3000	mreilly@gmocks.com	Principal Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448312	WELL	DG	11/19/2016		121-11062	WAR WAGON 1-24	DG

General Comment:

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	316-265-3000		
Corrective Action:		Date:	_____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Location Construction

Location ID: 448312 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: No problems seen.

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: 448312 Type: WELL API Number: 121-11062 Status: DG Insp. Status: DG

Well Drilling

Rig: Rig Name: WW Drilling Rig 20 Pusher/Rig Manager: Josh
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids

Management:

Lined Pit: YES Unlined Pit: YES Closed Loop: NO Semi-Closed Loop: YES
 Multi-Well: NO Disposal Location: ONSITE; Other-evaporate and bury

Comment: TD Surface at 403', set 8 5/8"-24# surface casing to 398'.

Corrective Action: _____ Date: _____

Cement

Cement Contractor

Contractor Name: Consolidated Contractor Phone: 785-672-8822

Surface Casing

Cement Volume (sx): 275 Circulate to Surface: YES
 Cement Fall Back: _____ Top Job, 1" Volume: NO

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____ Cement Volume (sx): _____

Good Return During Job: _____ Cement Type: _____

Comment: 15# cement

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	
Slope Roughening	Pass					
Berms	Pass	Other	Pass	Material Handling And Spill Prevention	Pass	other-vegetation
Ditches	Pass	Tracking Pad	Pass	Self Inspection	Pass	

Comment: Top soil piles and all berms are compacted.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Drilling Pit Lined: NO Pit ID: Lat: 39.602600 Long: -103.375240

Reference Point: SE Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: c

Fencing:

Fencing Type: None Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date: _____

Type: Water Fresh Lined: YES Pit ID: Lat: 39.602440 Long: -103.375400

Reference Point: SE Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Plastic Liner Condition: Adequate

Comment:

Corrective Action

Date: c

Fencing:

Fencing Type: None Fencing Condition: _____

Comment: Corrective Action Netting:		Date:
Netting Type:	Netting Condition:	
Comment: Corrective Action		Date:
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment: Corrective Action		Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673714463	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4009541
673714466	Grand Mesa War Wagon sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4009533