

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/22/2016

Submitted Date:

11/22/2016

Document Number:

681901742**FIELD INSPECTION FORM**
 Loc ID 333138 Inspector Name: HELGELAND, GARY On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 68710Name of Operator: PETERSON ENERGY OPERATING INCAddress: 2154 W EISENHOWER BLVDCity: LOVELAND State: CO Zip: 80537**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|-------|----------------------------------|---------|
| Peterson, Andy | /8960 | andy.peterson@petersonenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 240805 | WELL | PR | 07/01/2014 | OW | 123-08593 | RASMUSSEN 1 | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|--------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | SATISFACTORY | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: SATISFACTORY

Corrective Action: _____ Date: _____

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

| | | | |
|--------------------|----------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | PANEL | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Other | # | | |
| Comment: | Refer to inspection # 681901741 for information concerning shared battery and equipment. | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | SATISFACTORY | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | |
|--------------------|--|----------|------|----------|--------|
| Contents | # | Capacity | Type | Tanak ID | SE GPS |
| | | | | | |
| Comment: | Refer to inspection # 681901741 for information concerning shared battery and equipment. | | | | |
| Corrective Action: | | Date: | | | |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | |
|------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|

| | | | | | |
|--------------------|--|--|--|--|-------|
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|--|--|-------|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|----------------------------------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 240805 | Type: | WELL | API Number: | 123-08593 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | PR | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |
| BradenHead | | | | | | | | | |
| Comment: | | Bradenhead is plumed to surface. | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

| Environmental | |
|------------------------------------|--|
| Spill/Remediation: | |
| Comment: | |
| Corrective Action: | Date: |
| Emission Control Burner (ECB): YES | |
| Comment: | |
| Pilot: OFF | Wildlife Protection Devices (fired vessels): YES |

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass Segregated soils have been replaced? _____**RESTORATION AND REVEGETATION**CroplandTop soil replaced Pass Recontoured Pass Perennial forage re-established InNon-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation In Process**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 681901742 | INSPECTION APPROVED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4014001 |